



GREEN AUCTION

MINI EXCAVATOR

LotNo	1133012	LOCATION	YOKOHAMA-E*
MAKER	KOMATSU	YEAR	—
MODEL	PC38UU-3	HOURL	1823
S/N	9712		

☐ DOCUMENT/書類 ☐ UNABLE TO TRAVEL(START)/不動車

ENGINE	MODEL	3D84E-3MB1
	S/N	46475
	COOLANT	OK
	OIL	OK
	START	OK
	BLOW-BY	NO / なし
	NOISE	NO / なし
	EPA	NO / なし
	NOTE	

UNDERCARRIAGE	SHOE	TYPE	RUBBER
	☐ W/PAD		
	300 mm	OK	
	PIN BUSH	—	
	CARRIER ROLLER	OK	
	TRACK ROLLER	OK	
	FRONT IDLER	OK	
	SPROCKET	OK	
	NOTE		

FRONT ATTACHMENT	BOOM	TYPE	OFF-SET
		OK	
	ARM	TYPE	STD
		OK	
	PIPING	—	
	BUCKET	TYPE	STD
		OK	
	BLADE	OK	
	PINS	BOOM	OK
		ARM	OK
		BUCKET	OK
	NOTE		

CAB/CNP	CAB/CNP	OK
	ROPS	NO / なし
	SEAT	OK
	CONTROL LEVER	OK
	A/C OR HEATER	—
	COMPUTER	—
	MONITOR	LCD FADED / 液晶色褪せ
	BATTERY	OK
	NOTE	

CYLINDERS	BOOM	OK
	SWING	—
	ARM	OK
	BUCKET	OK
	BLADE	OK
	NOTE	

TURN TABLE	OK
------------	----

CONTROL	HYDRAULIC PUMP	OK
	TRAVEL	OK
	SWING	—
	CONTROL	OK
	NOTE	

ATTACHMENT	—
------------	---

REMARK

STAMPED SERIAL NUMBER UNKNOWN / 機械打刻未確認
BODY RUSTY/本体錆

HOUR MATER UNCERTAINTY / アワーメーター不確実

ATTENTION/注意 *For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
*別途修理、洗車の費用がかかる場合があります。ご了承くださいますようお願いいたします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
*Starting from 1st August 2017,for each successful bid a "Successful Bid Fee" will be charged
*2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました