



GREEN AUCTION

EXCAVATOR

LotNo	2134006	LOCATION	KOBE-N
MAKER	YANMAR	YEAR	2012
MODEL	SV100-1	HOURL	4097
S/N	11564		

☐ DOCUMENT/書類 ☐ UNABLE TO TRAVEL(START)/不働車

ENGINE	MODEL	—
	S/N	—
	COOLANT	OK
	OIL	OK
	START	OK
	BLOW-BY	YES / あり (SLIGHTLY/小)
	NOISE	NO / なし
	EPA	YES / あり
	NOTE	

UNDERCARRIAGE	SHOE	TYPE	STEEL
	☒ W/PAD		
	475 mm	OK	
	PIN BUSH	OK	
	CARRIER ROLLER	OK	
	TRACK ROLLER	OK	
	FRONT IDLER	OK	
	SPROCKET	OK	
	NOTE		

FRONT ATTACHMENT	BOOM	TYPE	SWING
			BENT AT BOOM FAR END, SLIGHTLY OPEN / 先端開き
	ARM	TYPE	STD
			OK
	PIPING	—	
	BUCKET	TYPE	STD
			OK
	BLADE	OK	
	PINS	BOOM	OK
		ARM	LOOSE (SLIGHT) / ガタ (小)
		BUCKET	OK
	NOTE		

CAB/CNP	CAB/CNP	OK
	ROPS	NO / なし
	SEAT	OK
	CONTROL LEVER	OK
	A/C OR HEATER	OK
	COMPUTER	OK
	MONITOR	OK
	BATTERY	OK
	NOTE	

CYLINDERS	BOOM	OIL LEAK / オイル漏れ (SLIGHT / 小)
	SWING	OK
	ARM	OK
	BUCKET	OK
	BLADE	OK
	NOTE	

TURN TABLE	OK
------------	----

CONTROL	HYDRAULIC PUMP	OK
	TRAVEL	OK
	SWING	OK
	CONTROL	OK
	NOTE	

ATTACHMENT	—
------------	---

REMARK
4WAY MULTI LEVER / 4WAYマルチレバー 2.9T ARM CRANE / クレーン付き

ATTENTION/注意 *For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
*別途修理、洗車の費用がかかる場合があります。ご了承くださいますようお願いいたします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
*Starting from 1st August 2017,for each successful bid a "Successful Bid Fee" will be charged
*2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました