



GREEN AUCTION

LotNo	2134001	LOCATION	HAKATA-A
-------	---------	----------	----------

MAKER	KOMATSU	YEAR	2003
MODEL	PC70-7C	HOURL	16738
S/N	59866		

EXCAVATOR

134th Internet Auction 2025/10/23 ~ 2025/10/24

☐ DOCUMENT/書類 ☐ UNABLE TO TRAVEL(START)/不働車

ENGINE	MODEL	4D95LE-2
	S/N	108414
	COOLANT	OK
	OIL	OK
	START	OK
	BLOW-BY	NO/なし
	NOISE	NO/なし
	EPA	YES/あり
	NOTE	

UNDERCARRIAGE	SHOE	TYPE	STEEL
	☐ W/PAD	OK	
	450 mm		
	PIN BUSH	OK	
	CARRIER ROLLER	OK	
	TRACK ROLLER	OK	
	FRONT IDLER	OK	
	SPROCKET	OK	
	NOTE	BOTH SIDES TRAVEL MOTOR MINOR OIL LEAKING. 左右走行モーター 油にじみ	

FRONT ATTACHMENT	BOOM	TYPE	LONG
		OK	
	ARM	TYPE	STD
		OK	
	PIPING	-	
	BUCKET	TYPE	SLOPE
		OK	
	BLADE	OK	
	PINS	BOOM	OK
		ARM	LOOSE/ガタ(SLIGHTLY/小)
		BUCKET	LOOSE/ガタ(SLIGHTLY/小)
	NOTE		

CAB/CNP	CAB/CNP	OK
	ROPS	NO/なし
	SEAT	TORN/破れ
	CONTROL LEVER	OK
	A/C OR HEATER	OK
	COMPUTER	OK
	MONITOR	OK
	BATTERY	OK
	NOTE	

CYLINDERS	BOOM	OK
	SWING	-
	ARM	OK
	BUCKET	OIL LEAKING SLIGHTLY/オイル漏れ小 SCRATCHED/傷
	BLADE	OK
	NOTE	

TURN TABLE	OK
------------	----

CONTROL	HYDRAULIC PUMP	OK
	TRAVEL	OK
	SWING	LOOSE/ガタ(SLIGHTLY/小)
	CONTROL	OK
	NOTE	

ATTACHMENT	OK
------------	----

REMARK

NEED WASHING./要洗車

ATTENTION/注意

*For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
*別途修理、洗車の費用がかかる場合があります。ご了承くださいませうお願いします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
*Starting from 1st August 2017,for each successful bid a " Successful Bid Fee" will be charged
*2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました