



GREEN AUCTION

MANLIFT

LotNo	8256001	LOCATION	KOBE-N
-------	---------	----------	--------

MAKER	AICHI	YEAR	2019				
MODEL	WM05C1NS	HOUR	180	CARRIER HR	—	CARRIER KM	—
S/N	789836	CASSIS MODEL	—	CASSIS S/N	—		

☐ DOCUMENT/書類 ☒ UNABLE TO TRAVEL(START)/不動態

ENGINE	CARRIER		CRANE		HYDRAULIC (CRANE)	PUMP	—	TYPE OF OUTRIGGER	—	ELECTRICAL	LIGHT	—		
	MODEL	—	—	MAIN WINCH		—	OUTRIGGER CYLINDER	—	WIPER		—			
	S/N	—	—	AUX WINCH		—	OUTRIGGER EXTENSION	—	HEATER		—			
	COOLANT	—	—	BOOM EXTENSION		—	SWING	—	A/C		—			
	OIL	—	—	BOOM HOIST		—	CONTROL LEVER	—	BATTERY		—			
	START	—	—	NOTE					NOTE					
	BLOW-BY	—	—											
	NOISE	—	—											
	NOTE													
HOOK	CAPACITY	MAIN	— (t)	SUB	— (t)	BOOM	LENGTH	—	m	TIRE	SIZE	—		
	NO. OF HOOK	—		pcs	CONDITION		OK		SHOE		TYPE	—		
	WIRE ROPE	—			☐ W/PAD						PIN BUSH			
	NOTE				—		mm					CARRIER ROLLER	—	
TRANSMISSION	NO. OF SPEED	F	—	R	—	JIB	NO. OF SEC	—	sec	UNDERCARRIAGE	TRACK ROLLER	—		
	SHIFT	—			CONDITON		—		FRONT IDLER		—			
	OIL	—			NOTE				SPROCKET		—			
	NOTE													
CAB	—		SAFETY DEVICE	MONITOR	—		FORK LIFT	TYPE	—		REMARK			
	SEAT	—		AML	—			FORK	LENGTH	—		mm	MAX FLOOR HEIGHT : 4.8M BODY DAMAGED / ボディ損傷あり、ゆがみ UNABLE TO TRAVEL(START)/不動態	
	NOTE			OVER WIND CUT	—			MAST	LENGTH	—		mm		
				NOTE	DISPLAY "LMT001/002" / エラー表示あり									
CAB	—		SAFETY DEVICE	MONITOR	—		BRAKE	FOOT	—		REMARK			
	SEAT	—		AML	—			PARKING	—					
	NOTE			OVER WIND CUT	—			NOTE						

ATTENTION/ 注意

*For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.

*別途修理、洗車の費用がかかる場合があります。ご了承くださいますようお願いいたします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。

*Starting from 1st August 2017,for each successful bid a "Successful Bid Fee" will be charged

*2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました