



GREEN AUCTION

EXCAVATOR

LotNo	2257008	LOCATION	KOBE-N
MAKER	KOMATSU	YEAR	2003
MODEL	PC228US-3N0	HOURL	UNKNOWN
S/N	30077		

☐ DOCUMENT/書類 ☐ UNABLE TO TRAVEL(START)/不働車

ENGINE	MODEL	—
	S/N	—
	COOLANT	OK
	OIL	OK
	START	OK
	BLOW-BY	YES / あり (SLIGHTLY/小)
	NOISE	NO / なし
	EPA	NO / なし
	NOTE	FUEL LEAK, DROP / 燃料漏れ

UNDERCARRIAGE	SHOE	TYPE	STEEL
	<input type="checkbox"/> W/PAD		
	600 mm	OK	
	PIN BUSH	OK	
	CARRIER ROLLER	OK	
	TRACK ROLLER	OK	
	FRONT IDLER	OK	
	SPROCKET	OK	
	NOTE		

FRONT ATTACHMENT	BOOM	TYPE	STD
			OK
	ARM	TYPE	STD
			OK
	PIPING	RUST, CONTROL NG / サビ、操作不良	
	BUCKET	TYPE	SKELETON
			OK
	BLADE	—	
	PINS	BOOM	OK
		ARM	OK
		BUCKET	OK
	NOTE		

CAB/CNP	CAB/CNP	DAMAGED / 損傷	
	ROPS	NO / なし	
	SEAT	DEFECT / 破れ	
	CONTROL LEVER	OK	
	A/C OR HEATER	—	
	COMPUTER	—	
	MONITOR	DEFECT / 不良	
	BATTERY	OK	
	NOTE		

CYLINDERS	BOOM	RIGHT, MINOR OIL LEAK / 右側オイルにじみ	
	SWING	—	
	ARM	OK	
	BUCKET	OK	
	BLADE	—	
	NOTE		

TURN TABLE	LOOSE (SLIGHT) / ガタ (小)
------------	-------------------------

CONTROL	HYDRAULIC PUMP	MINOR OIL LEAK / オイルにじみ	
	TRAVEL	OK	
	SWING	OK	
	CONTROL	OK	
	NOTE	CONTROL VALVE MINOR OIL LEAK / コントロールバルブオイルにじみ	

ATTACHMENT	—
------------	---

REMARK
FUEL LEAK, NEED WRAPPING WITH ABSORBENT MAT WHEN SHIPPING ON BULK CARRIER SHIP. / 燃料漏れにつき在来船輸出の場合は吸着マット処置必要 *NEED LIFT CHARGE FOR RELEASING. (出庫時、別途リフトチャージ必要) NEED WASHING / 要洗車

ATTENTION/注意 *For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
*別途修理、洗車の費用がかかる場合があります。ご了承くださいますようお願いいたします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
*Starting from 1st August 2017,for each successful bid a "Successful Bid Fee" will be charged
*2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました