



GREEN AUCTION

EXCAVATOR

LotNo	2257003	LOCATION	KOBE-N
MAKER	KOMATSU	YEAR	2013
MODEL	PC128US-8	HOURL	6483
S/N	30565		

☐ DOCUMENT/書類 ☐ UNABLE TO TRAVEL(START)/不働車

ENGINE	MODEL	SAA4D95LE-5
	S/N	541752
	COOLANT	OK
	OIL	OK
	START	OK
	BLOW-BY	NO / なし
	NOISE	NO / なし
	EPA	NO / なし
	NOTE	CHARGING DEFECT / 充電不良

UNDERCARRIAGE	SHOE	TYPE	STEEL
	☒ W/PAD		
	500 mm	OK	
	PIN BUSH	OK	
	CARRIER ROLLER	OK	
	TRACK ROLLER	OK	
	FRONT IDLER	OK	
	SPROCKET	OK	
	NOTE		

FRONT ATTACHMENT	BOOM	TYPE	STD
			OK
	ARM	TYPE	STD
			OK
	PIPING		—
	BUCKET	TYPE	STD
			OK
	BLADE		—
	PINS	BOOM	OK
		ARM	LOOSE (SLIGHT) / ガタ (小)
		BUCKET	OK
	NOTE		

CAB/CNP	CAB/CNP	OK
	ROPS	YES / あり
	SEAT	WORN / 破れ
	CONTROL LEVER	OK
	A/C OR HEATER	OK
	COMPUTER	OK
	MONITOR	OK
	BATTERY	WEAK / 弱い
	NOTE	SOME COVERS BENT / カバー曲がり

CYLINDERS	BOOM	OK
	SWING	—
	ARM	OK
	BUCKET	OK
	BLADE	—
	NOTE	

TURN TABLE	OK
------------	----

CONTROL	HYDRAULIC PUMP	OK
	TRAVEL	OK
	SWING	OK
	CONTROL	OK
	NOTE	4WAY MULTI LEVER / 4WAYマルチレバー

ATTACHMENT	—
------------	---

REMARK
2.9TON ARM CRANE / クレーン付き

ATTENTION/注意 *For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
*別途修理、洗車の費用がかかる場合があります。ご了承くださいますようお願いいたします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
*Starting from 1st August 2017,for each successful bid a "Successful Bid Fee" will be charged
*2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました