



GREEN AUCTION

LotNo	2257002	LOCATION	HAKATA-A
-------	---------	----------	----------

MAKER	KOMATSU	YEAR	1993
MODEL	PC120-6	HOURL	10661
S/N	45264		

EXCAVATOR

157th Tender Auction 2025/12/11 ~ 2025/12/12

☐ DOCUMENT/書類 ☐ UNABLE TO TRAVEL(START)/不働車

ENGINE	MODEL	S4D95L-1	
	S/N	153359	
	COOLANT	OK	
	OIL	OK	
	START	OK	
	BLOW-BY	NO/なし	
	NOISE	NO/なし	
	EPA	NO/なし	
	NOTE		

UNDERCARRIAGE	SHOE	TYPE	STEEL
	<input type="checkbox"/> W/PAD	OK	
	500 mm		
	PIN BUSH	OK	
	CARRIER ROLLER	OK	
	TRACK ROLLER	OK	
	FRONT IDLER	OK	
	SPROCKET	OK	
	NOTE		

FRONT ATTACHMENT	BOOM	TYPE	STD
		OK	
	ARM	TYPE	STD
		OK	
	PIPING	-	
	BUCKET	TYPE	STD
		OK	
	BLADE	-	
	PINS	BOOM	OK
		ARM	OK
		BUCKET	OK
	NOTE		

CAB/CNP	DOOR NOT CLOSE.ドア閉まらない
ROPS	NO/なし
SEAT	TORN/破れ
CONTROL LEVER	OK
A/C OR HEATER	OK
COMPUTER	OK
MONITOR	DEFECT/不良
BATTERY	DEAD/あがり
NOTE	CORRODED SEVERELY. 腐食多い

CYLINDERS	BOOM	OK
	SWING	-
	ARM	OK
	BUCKET	OK
	BLADE	-
	NOTE	

TURN TABLE	OK
------------	----

CONTROL	HYDRAULIC PUMP	OIL LEAKING MODERATELY/オイル漏れ中
	TRAVEL	OK
	SWING	OK
	CONTROL	OK
	NOTE	

ATTACHMENT	-
------------	---

REMARK

OIL LEAKING. NEED REPAIR. NEED WASHING. 油漏れ 要修理 要洗車

ATTENTION/注意

*For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
*別途修理、洗車の費用がかかる場合があります。ご了承くださいませうお願いします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
*Starting from 1st August 2017,for each successful bid a " Successful Bid Fee" will be charged
*2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました