



GREEN AUCTION

EXCAVATOR

LotNo	2258011	LOCATION	KOBE-N
MAKER	KOBELCO	YEAR	2015
MODEL	SK135SRD-3	HOURL	5560
S/N	YY07-27475		

☐ DOCUMENT/書類 ☐ UNABLE TO TRAVEL(START)/不働車

ENGINE	MODEL	—
	S/N	—
	COOLANT	BLOW. NOT ENOUGH. / 吹き出す, 不足
	OIL	OK
	START	OK
	BLOW-BY	YES / あり
	NOISE	NO / なし
	EPA	NO / なし
	NOTE	OVERHEAT / オーバーヒート

UNDERCARRIAGE	SHOE	TYPE	STEEL
	☐ W/PAD		
	500 mm	OK	
	PIN BUSH	OK	
	CARRIER ROLLER	BROKE (RIGHT) / 右、不良	
	TRACK ROLLER	OK	
	FRONT IDLER	OK	
	SPROCKET	OK	
	NOTE		

FRONT ATTACHMENT	BOOM	TYPE	STD
			OK
	ARM	TYPE	STD
			OK
	PIPING	OK	
	BUCKET	TYPE	STD
			OK
	BLADE	—	
	PINS	BOOM	OK
		ARM	OK
		BUCKET	OK
	NOTE	2.9TON ARM CRANE / クレーン付き	

CAB/CNP	CAB/CNP	OK
	ROPS	NO / なし
	SEAT	COVERED / シートカバー
	CONTROL LEVER	OK
	A/C OR HEATER	—
	COMPUTER	CRANE ERROR / クレーンモード不良
	MONITOR	OK
	BATTERY	OK
	NOTE	B163: (DISCONNECTION OF P1SIDE PRESSURE SENSOR.) INDICATE / B163表示

CYLINDERS	BOOM	OK
	SWING	—
	ARM	OK
	BUCKET	OK
	BLADE	—
	NOTE	

TURN TABLE	OK
------------	----

CONTROL	HYDRAULIC PUMP	OK
	TRAVEL	OK
	SWING	OK
	CONTROL	OK
	NOTE	4WAY MULTI LEVER / 4WAYマルチレバー

ATTACHMENT	—
------------	---

REMARK
PLEASE CHECK THE PUNCHED SERIAL NUMBER / 刻印要確認 MACHINE OVERHEAT BE CAREFUL / オーバーヒート注意

ATTENTION/注意 *For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
*別途修理、洗車の費用がかかる場合があります。ご了承くださいますようお願いいたします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
*Starting from 1st August 2017,for each successful bid a "Successful Bid Fee" will be charged
*2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました