



GREEN AUCTION

FORK LIFT

LotNo	7258004	LOCATION	KOBE-N
-------	---------	----------	--------

MAKER	KOMATSU	YEAR	1993				
MODEL	FD100-5	HR	1102	CARRIER	—	CARRIER	—
S/N	4014	CASSIS	M114	CASSIS	M114-4014		

☐ DOCUMENT/書類 ☐ UNABLE TO TRAVEL(START)/不働車

ENGINE	CARRIER	CRANE		HYDRAULIC (CRANE)	PUMP	OK	TYPE OF OUTRIGGER	—	ELECTRICAL	LIGHT	—	
	MODEL	6D105	—		MAIN WINCH	—	OUTRIGGER CYLINDER	—		WIPER	—	
	S/N	6D105-117504	—		AUX WINCH	—	OUTRIGGER EXTENSION	—		HEATER	—	
	COOLANT	OK	—		BOOM EXTENSION	—	SWING	—		A/C	—	
	OIL	NOT ENOUGH / 不足気味	—		BOOM HOIST	—	CONTROL LEVER	OK		BATTERY	DEAD / あがり	
	START	OK	—		NOTE					NOTE	CHARGING DEFECT / 充電不良 ENGINE STOP DEFECT / エンジン停止不良	
	BLOW-BY	NO / なし	—									
	NOISE	NO / なし	—									
NOTE	WHITE SMOKE EXHAUST / 排気白煙 OIL PAN DENT / オイルパンへこみ											
HOOK	CAPACITY	MAIN	— (t)	SUB	— (t)	BOOM	LENGTH	—	m	TIRE	SIZE	9.00-20
	NO. OF HOOK	—			pcs		CONDITION	OK	SHOE		TYPE	—
	WIRE ROPE	—						<input type="checkbox"/> W/PAD				
	NOTE											
TRANSMISSION	NO. OF SPEED	F	2	R	2	JIB	NO. OF SEC	—	sec	UNDERCARRIAGE	PIN BUSH	—
	SHIFT	OK					CONDITON	—	CARRIER ROLLER		—	
	OIL	OK					NOTE		TRACK ROLLER		—	
	NOTE								FRONT IDLER		—	
CAB	OK	SAFETY DEVICE	MONITOR	—	FORK LIFT	HYDRAULIC	TYPE	—	BRAKE	FOOT	OK	
	SEAT		OK	AML			—	PARKING		OK		
	NOTE			OVER WIND CUT			—	NOTE				
REMARK												
10T												

ATTENTION/ 注意

*For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.

*別途修理、洗車の費用がかかる場合があります。ご了承くださいますようお願いいたします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。

*Starting from 1st August 2017,for each successful bid a "Successful Bid Fee" will be charged

*2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました