



GREEN AUCTION

LotNo	2136005	LOCATION	HAKATA-S
-------	---------	----------	----------

EXCAVATOR

136th Internet Auction 2026/01/29 ~ 2026/01/30

MAKER	KOMATSU	YEAR	2010
MODEL	PC128US-8	HOUR	462
S/N	25794		

 DOCUMENT/書類
 UNABLE TO TRAVEL(START)/不働車

ENGINE	MODEL	-
	S/N	-
	COOLANT	OK
	OIL	OK
	START	OK
	BLOW-BY	YES/あり(SLIGHTLY/小)
	NOISE	NO/なし
	EPA	YES/あり
	NOTE	

FRONT ATTACHMENT	BOOM	TYPE	STD
			OK
	ARM	TYPE	STD
			OK
	PIPING		OK
	BUCKET	TYPE	SLOPE
			OK
	BLADE		-
	PINS	BOOM	LOOSE/ガタ
		ARM	LOOSE/ガタ
	BUCKET	LOOSE/ガタ	
NOTE			

CYLINDERS	BOOM	OK
	SWING	OK
	ARM	OK
	BUCKET	OK
	BLADE	OK
	NOTE	

TURN TABLE	LOOSE LATERALLY/横ガタ
------------	---------------------

CONTROL	HYDRAULIC PUMP	OK
	TRAVEL	OK
	SWING	OK
	CONTROL	OK
	NOTE	

ATTACHMENT	-
------------	---

REMARK	BODY PUNCHED S/N UNKNOWN./刻印不明不明
--------	----------------------------------

UNDERCARRIAGE	SHOE	TYPE	STEEL
	<input type="checkbox"/> W/PAD		OK
	500 mm		
	PIN BUSH		OK
	CARRIER ROLLER		OK
	TRACK ROLLER	MINOR OIL LEAK / 油にじみ(LEFT 2pcs. RIGHT 1pc.)	
	FRONT IDLER		OK
	SPROCKET		OK
NOTE			

CAB/CNP	CAB/CNP	OK
	ROPS	YES/あり
	SEAT	TORN/破れ
	CONTROL LEVER	OK
	A/C OR HEATER	ERROR INDICATING.エラー表示あり
	COMPUTER	OK
	MONITOR	OK
	BATTERY	NG
NOTE	COVER RUSTY, SCRATCHED. カバー錆 傷	

ATTENTION/注意

*For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
 *別途修理、洗車の費用がかかる場合があります。ご了承くださいませうお願いします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
 *Starting from 1st August 2017,for each successful bid a " Successful Bid Fee" will be charged
 *2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました