



GREEN AUCTION

MANLIFT

LotNo	8137001	LOCATION	KOBE-N
-------	---------	----------	--------

MAKER	AICHI	YEAR	2019				
MODEL	WM05C1NS	HOUR	180	CARRIER HR	—	CARRIER KM	—
S/N	789836	CASSIS MODEL	—	CASSIS S/N	—		

☐ DOCUMENT/書類 ☒ UNABLE TO TRAVEL(START)/不動態

ENGINE	CARRIER		CRANE		HYDRAULIC (CRANE)	PUMP	—	TYPE OF OUTRIGGER	—	ELECTRICAL	LIGHT	—
	MODEL	—	—	MAIN WINCH		—	OUTRIGGER CYLINDER	—	WIPER		—	
	S/N	—	—	AUX WINCH		—	OUTRIGGER EXTENSION	—	HEATER		—	
	COOLANT	—	—	BOOM EXTENSION		—	SWING	—	A/C		—	
	OIL	—	—	BOOM HOIST		—	CONTROL LEVER	—	BATTERY		—	
	START	—	—	NOTE					NOTE			
	BLOW-BY	—	—									
	NOISE	—	—									
	NOTE											
HOOK	CAPACITY	MAIN	— (t)	SUB	— (t)	BOOM	LENGTH	—	m	TIRE	SIZE	—
	NO. OF HOOK	—		pcs	CONDITION		OK					
	WIRE ROPE	—			SHOE		TYPE		—			
	NOTE				☐ W/PAD							
TRANSMISSION	NO. OF SPEED	F	—	R	—	JIB	NO. OF SEC	—	sec	UNDERCARRIAGE	PIN BUSH	—
	SHIFT	—			CONDITON		—		CARRIER ROLLER		—	
	OIL	—			NOTE				TRACK ROLLER		—	
	NOTE								FRONT IDLER		—	
CAB	—				SAFETY DEVICE	MONITOR	—		REMARK	MAX FLOOR HEIGHT : 4.8M BODY DAMAGED / ボディ損傷あり、ゆがみ UNABLE TO TRAVEL(START)/不動態		
	SEAT	—				AML	—					
	NOTE					OVER WIND CUT	—					
						NOTE	DISPLAY "LMT001/002" / エラー表示あり					
FORK LIFT	HYDRAULIC	TYPE	—		BRAKE	FOOT	—					
		FORK	LENGTH	—		mm	PARKING	—				
		MAST	LENGTH	—		mm	NOTE					
		LIFT CYLINDER	—									
TILT CYLINDER	—											
HOIST CYLINDER	—											
NOTE												

ATTENTION/ 注意

*For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.

*別途修理、洗車の費用がかかる場合があります。ご了承くださいますようお願いいたします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。

*Starting from 1st August 2017,for each successful bid a "Successful Bid Fee" will be charged

*2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました