



GREEN AUCTION

LotNo	1137012	LOCATION	KOBE-N
-------	---------	----------	--------

MAKER	IHI	YEAR	2007
-------	-----	------	------

MODEL	50Z	HOUR	3235
-------	-----	------	------

S/N	BN000664
-----	----------

DOCUMENT/書類 UNABLE TO TRAVEL(START)/不動車

MODEL	—
S/N	—
COOLANT	OK
OIL	OK
START	OK
BLOW-BY	NO / なし
NOISE	NO / なし
EPA	NO / なし
NOTE	MINOR OIL LEAK / オイルにじみ

SHOE	TYPE	STEEL
<input checked="" type="checkbox"/> W/PAD		
400 mm	OK	
PIN BUSH	OK	
CARRIER ROLLER	OK	
TRACK ROLLER	OK	
FRONT IDLER	OK	
SPROCKET	OK	
NOTE		

FRONT ATTACHMENT	BOOM	TYPE	OFF-SET	CYLINDERS	BOOM	MINOR OIL LEAK / オイルにじみ
	ARM	TYPE	STD		SWING	OK
	PIPING	OK			ARM	OK
		—			BUCKET	OK
	BUCKET	TYPE	STD		BLADE	OK
		OK			NOTE	
	BLADE	OK			TURN TABLE	OK
		BOOM	OK		HYDRAULIC PUMP	OK
		ARM	OK		TRAVEL	OK
	PINS	BUCKET	OK		SWING	OK
		NOTE			CONTROL	OK
CAB/CNP	CAB/CNP	OK		CONTROL	NOTE	4WAY MULTI LEVER / 4WAYマルチレバー
	ROPS	NO / なし			ATTACHMENT	—
	SEAT	WORN / 破れ			REMARK	
	CONTROL LEVER	OK			OIL LEAK FROM THE RIGHT DRIVE MOTOR COVER. SUSPECTED LEAK FROM THE HOSE INSIDE THE FRAME. / 右走行モーターカバーから油漏れ。フレーム内ホースの漏れ疑い	
	A/C OR HEATER	—			NEED WASHING FOR SHIPPING ON BULK CARRIER SHIP / 在来船輸出の場合は要洗車	
	COMPUTER	—				
	MONITOR	—				
	BATTERY	OK				
	NOTE					

ATTENTION/注意 *For unit required washing or repair, extra fee will be charge. The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
*別途修理、洗車の費用がかかる場合があります。ご了承くださいますようお願いします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
*Starting from 1st August 2017, for each successful bid a "Successful Bid Fee" will be charged
*2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました