



GREEN AUCTION

LotNo	9137023	LOCATION	KOBE-N
-------	---------	----------	--------

MAKER	DENYO	YEAR	—
MODEL	DCA-60LSIB	HOUR	7760
S/N	3870459	MILE	—

GENERATOR

 DOCUMENT/書類 UNABLE TO TRAVEL(START)/不動車

ENGINE	MODEL	—	GENERATOR/WELDER	RATED POWER	60	KVA
	S/N	—		RATED AMPERE	—	A
	COOLANT	OK		TERMINAL	—	
	OIL	OK		CIRCUIT BREAKER	—	
	START	NG		INSULATION	—	MΩ
	BLOW-BY	—		NOTE	NOT TESTED / 未確認	
	NOISE	—		RATED PRESS	—	Kgf/m² Mpa
	EPA	NO / なし		AIR VALVE	—	RATED AIR
ELECTRICAL	NOTE	THE STOP SOLENOID VALVE? NOT RECEIVING POWER / ストップソレノイドバルブ通電しない疑い		UNLOAD	—	m³/min
	LIGHTS	—		OIL	—	
	MONITOR	—		NOTE		
	SWITCH	—		BLANK		
	BATTERY	OK				
	NOTE					

OTHER ITEMS				NOTE
—	—	—	—	
—	—	—	—	
—	—	—	—	

ATTENTION/注意 *For unit required washing or repair, extra fee will be charge. The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
 *別途修理、洗車の費用がかかる場合があります。ご了承くださいますようお願いします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
 *Starting from 1st August 2017, for each successful bid a "Successful Bid Fee" will be charged
 *2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました

HYDRAULIC	PUMP	—	CAB/CNP
	HOPPER CYLINDER	—	
	PIVOT CYLINDER	—	
	SCREED CYLINDER (UP DOWN)	—	
	SCREED CYLINDER (EXTENDABLE)	—	
	CONTROL VALVE	—	
	NOTE		
UNDERCARRIAGE	IRON	WIDTH	— m
	EXTENSION IRON	WIDTH	— m
	SCREW(SUB)	—	
	NOTE		

FINISHER

REMARK
STARTER IS WORKING, BUT UNABLE TO START ENGINE. / セル回るがエンジン始動しない