



LotNo	1138007	LOCATION	KOBE-N
MAKER	YANMAR	YEAR	1992
MODEL	B50	HOURL	2809
S/N	01265B		

DOCUMENT/書類     UNABLE TO TRAVEL(START)/不働車

ENGINE	MODEL	-	
	S/N	-	
	COOLANT	OK	
	OIL	OK	
	START	OK	
	BLOW-BY	NO / なし	
	NOISE	NO / なし	
	EPA	NO / なし	
	NOTE		

FRONT ATTACHMENT	BOOM	TYPE	SWING
		OK	
	ARM	TYPE	STD
		OK	
	PIPING	-	
	BUCKET	TYPE	STD
		WORN / 摩耗	
	BLADE	OK	
	PINS	BOOM	OK
		ARM	OK
BUCKET		OK	
NOTE			

CYLINDERS	BOOM	MINOR OIL LEAK / オイルにじみ
	SWING	OK
	ARM	OK
	BUCKET	OK
	BLADE	OK
	NOTE	

TURN TABLE	OK
------------	----

CONTROL	HYDRAULIC PUMP	OK
	TRAVEL	OK
	SWING	OK
	CONTROL	OK
	NOTE	AB MULTI LEVER (2WAY) / ABマルチレバー

ATTACHMENT	-
------------	---

REMARK

UNDERCARRIAGE	SHOE	TYPE	STEEL
	<input type="checkbox"/> W/PAD		
	<input checked="" type="checkbox"/> 380 mm	OK	
	PIN BUSH	OK	
	CARRIER ROLLER	OK	
	TRACK ROLLER	OK	
	FRONT IDLER	OK	
	SPROCKET	OK	
NOTE			

CAB/CNP	CAB/CNP	CORRODED (SLIGHT) / 腐食(小)
	ROPS	NO / なし
	SEAT	DEFECT / 破れ
	CONTROL LEVER	OK
	A/C OR HEATER	-
	COMPUTER	-
	MONITOR	-
	BATTERY	DEAD / あがり
	NOTE	

ATTENTION/注意 \*For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.  
 \*別途修理、洗車の費用がかかる場合があります。ご了承くださいますようお願いいたします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。  
 \*Starting from 1st August 2017,for each successful bid a "Successful Bid Fee" will be charged  
 \*2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました