



LotNo	8138003	LOCATION	KOBE-N
-------	---------	----------	--------

MAKER	MITSUBISHI	YEAR	2007				
MODEL	AT-157CG (PA-FE73DB)	HOUR	4162	CARRIER HR	—	CARRIER KM	51550KM
S/N	375669 (FE73DB-523237)	CASSIS MODEL	PA-FE73DB	CASSIS S/N	FE73DB-523237		

DOCUMENT/書類 UNABLE TO TRAVEL(START)/不働車

ENGINE	CARRIER	CRANE	
	MODEL	4M50	—
	S/N	—	—
	COOLANT	OK	—
	OIL	OK	—
	START	OK	—
	BLOW-BY	NO / なし	—
	NOISE	NO / なし	—
	NOTE		

HYDRAULIC (CRANE)	PUMP	OK	TYPE OF OUTRIGGER	H-TYPE
	MAIN WINCH	—	OUTRIGGER CYLINDER	OK
	AUX WINCH	—	OUTRIGGER EXTENSION	OK
	BOOM EXTENSION	OK	SWING	OK
	BOOM HOIST	OK	CONTROL LEVER	OK
	NOTE			

ELECTRICAL	LIGHT	OK
	WIPER	OK
	HEATER	OK
	A/C	OK
	BATTERY	OK
	NOTE	

HOOK	CAPACITY	MAIN	—	(t)	SUB	—	(t)	
	NO. OF HOOK	—						pcs
	WIRE ROPE	—						
	NOTE							

BOOM	LENGTH	—	m
	CONDITION	—	
	SHEEVE	—	
	NOTE		

FORK LIFT	HYDRAULIC	TYPE	—		
		FORK	LENGTH	—	mm
			MAST	LENGTH	—
	LIFT CYLINDER	TILT CYLINDER	—		
		HOIST CYLINDER	—		
		NOTE			

TIRE	SIZE	205/85R15	
	CONDITION	OK	
UNDERCARRIAGE	SHOE	TYPE	—
	<input type="checkbox"/> W/PAD	—	
	PIN BUSH	—	
	CARRIER ROLLER	—	
	TRACK ROLLER	—	
	FRONT IDLER	—	
	SPROCKET	—	
NOTE			

TRANSMISSION	NO. OF SPEED	F	5	R	1
	SHIFT	OK			
	OIL	OK			
	NOTE	5M/T			

JIB	NO. OF SEC	—	sec
	CONDITON	—	
	NOTE		

CAB	OK
SEAT	OK
NOTE	

SAFTY DEVICE	MONITOR	OK
	AML	OK
	OVER WIND CUT	—
	NOTE	

BRAKE	FOOT	OK
	PARKING	OK
	NOTE	

REMARK	TADANO MANLIFT EXTRA RECYCLING FEE JPY 8,930/ リサイクル料
--------	---

ATTENTION/ 注意 *For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
 *別途修理、洗車の費用がかかる場合があります。ご了承くださいませようお願いします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
 *Starting from 1st August 2017,for each successful bid a "Successful Bid Fee" will be charged
 *2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました