



LotNo	7259006	LOCATION	KOBE-N
-------	---------	----------	--------

MAKER	TOYOTA	YEAR	2017				
MODEL	02-8FD20	HOUR	3690	CARRIER HR	—	CARRIER KM	—
S/N	A8FD25-66596	CASSIS MODEL	—	CASSIS S/N	—		

DOCUMENT/書類 UNABLE TO TRAVEL(START)/不働車

ENGINE	CARRIER	CRANE	HYDRAULIC (CRANE)	PUMP	OK	TYPE OF OUTRIGGER	—	
	MODEL	1ZS		—	MAIN WINCH	—	OUTRIGGER CYLINDER	—
	S/N	—		—	AUX WINCH	—	OUTRIGGER EXTENSION	—
	COOLANT	OK		—	BOOM EXTENSION	—	SWING	—
	OIL	OK		—	BOOM HOIST	—	CONTROL LEVER	OK
	START	OK		—	NOTE			
	BLOW-BY	NO / なし		—				
	NOISE	NO / なし		—				
	NOTE							

ELECTRICAL	LIGHT	OK
	WIPER	—
	HEATER	—
	A/C	—
	BATTERY	DEAD / あがり
NOTE		

HOOK	CAPACITY	MAIN	— (t)	SUB	— (t)
	NO. OF HOOK		—		pcs
	WIRE ROPE		—		
	NOTE				

BOOM	LENGTH	—	m
	CONDITION	—	
	SHEEVE	—	
	NOTE		

FORK LIFT	HYDRAULIC	TYPE	W/ATTACHMENT
		FORK	LENGTH 1510 mm
			OK
		MAST	LENGTH 3000 mm
			OK
	LIFT CYLINDER	OK	
	TILT CYLINDER	OK	
	HOIST CYLINDER	OK	
	NOTE	FORK SHIFTER (LEFT/RIGHT INDEPENDENT) / 左右独立式フォークポジショナー付き	

UNDERCARRIAGE	TIRE	SIZE	—
		CONDITION	OK
	SHOE	TYPE	—
		W/PAD	— mm
	PIN BUSH		—
	CARRIER ROLLER		—
	TRACK ROLLER		—
	FRONT IDLER		—
SPROCKET		—	
NOTE		SORID TIRES / ソリッドタイヤ	

TRANSMISSION	NO. OF SPEED	F	1	R	1
	SHIFT	OK			
	OIL	OK			
	NOTE				

JIB	NO. OF SEC	—	sec
	CONDITON	—	
	NOTE		

CAB	OK
SEAT	DAMAGED / えぐれ
NOTE	

SAFETY DEVICE	MONITOR	OK
	AML	—
	OVER WIND CUT	—
	NOTE	

BRAKE	FOOT	OK
	PARKING	OK
	NOTE	

REMARK	RUSTY, CORRODED. / サビ, 腐食 PUNCHED NUMBER CORRODED / 刻印腐食
--------	---

ATTENTION/ 注意 *For unit required washing or repair, extra fee will be charge. The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
 *別途修理、洗車の費用がかかる場合があります。ご了承くださいませようお願いします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
 *Starting from 1st August 2017, for each successful bid a "Successful Bid Fee" will be charged
 *2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました