



LotNo	8259003	LOCATION	KOBE-N
-------	---------	----------	--------

MAKER	MITSUBISHI	YEAR	2007				
MODEL	AT-157CG (PA-FE73DB)	HOUR	4162	CARRIER HR	-	CARRIER KM	51550KM
S/N	375669 (FE73DB-523237)	CASSIS MODEL	PA-FE73DB	CASSIS S/N	FE73DB-523237		

DOCUMENT/書類 UNABLE TO TRAVEL(START)/不働車

ENGINE	CARRIER	CRANE	HYDRAULIC (CRANE)	PUMP	OK	TYPE OF OUTRIGGER	H-TYPE	ELECTRICAL	LIGHT	OK
	MODEL	4M50		MAIN WINCH	-	OUTRIGGER CYLINDER	OK		WIPER	OK
	S/N	-		AUX WINCH	-	OUTRIGGER EXTENSION	OK		HEATER	OK
	COOLANT	OK		BOOM EXTENSION	OK	SWING	OK		A/C	OK
	OIL	OK		BOOM HOIST	OK	CONTROL LEVER	OK		BATTERY	OK
	START	OK		NOTE					NOTE	
	BLOW-BY	NO / なし								
	NOISE	NO / なし								
NOTE										

HOOK	CAPACITY	MAIN	-	(t)	SUB	-	(t)	
	NO. OF HOOK	-						pcs
	WIRE ROPE	-						
	NOTE							

BOOM	LENGTH	-	m
	CONDITION	-	
	SHEEVE	-	
	NOTE		

FORK LIFT	TYPE	-		
		FORK	LENGTH	-
	MAST	LENGTH	-	mm
		-		
HYDRAULIC	LIFT CYLINDER	-		
	TILT CYLINDER	-		
	HOIST CYLINDER	-		
	NOTE			

TIRE	SIZE	205/85R15		
	CONDITION	OK		
UNDERCARRIAGE	SHOE	TYPE	-	
	<input type="checkbox"/> W/PAD	-		
	-		mm	-
	PIN BUSH	-		
	CARRIER ROLLER	-		
	TRACK ROLLER	-		
	FRONT IDLER	-		
SPROCKET	-			
NOTE				

TRANSMISSION	NO. OF SPEED	F	5	R	1
	SHIFT	OK			
	OIL	OK			
	NOTE	5M/T			

JIB	NO. OF SEC	-	sec
	CONDITON	-	
	NOTE		

CAB	OK
SEAT	OK
NOTE	

SAFTY DEVICE	MONITOR	OK
	AML	OK
	OVER WIND CUT	-
	NOTE	

BRAKE	FOOT	OK
	PARKING	OK
	NOTE	

REMARK	TADANO MANLIFT EXTRA RECYCLING FEE JPY 8,930/ リサイクル料
--------	---

ATTENTION/ 注意 *For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
 *別途修理、洗車の費用がかかる場合があります。ご了承くださいませようお願いします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
 *Starting from 1st August 2017,for each successful bid a "Successful Bid Fee" will be charged
 *2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました