



LotNo	1259024	LOCATION	KOBE-N
MAKER	KUBOTA	YEAR	—
MODEL	U-45	HOOR	3157
S/N	11645		

DOCUMENT/書類 UNABLE TO TRAVEL(START)/不働車

ENGINE	MODEL	V2203
	S/N	—
	COOLANT	OK
	OIL	OK
	START	OK
	BLOW-BY	NO / なし
	NOISE	NO / なし
	EPA	NO / なし
	NOTE	FUEL LEAK FROM INJECTION LINE / 燃料漏れ

FRONT ATTACHMENT	BOOM	TYPE	SWING
			OK
	ARM	TYPE	STD
			REINFORCEMENT (TWO) / 二面補強
	PIPING		OK
	BUCKET	TYPE	STD
			OK
	BLADE		OK
	PINS	BOOM	OK
		ARM	OK
	BUCKET	OK	
NOTE			

CYLINDERS	BOOM	OK
	SWING	OK
	ARM	OK
	BUCKET	OK
	BLADE	OK
	NOTE	

TURN TABLE	OK
------------	----

CONTROL	HYDRAULIC PUMP	OK
	TRAVEL	OK
	SWING	OK
	CONTROL	OK
NOTE	THE LEFT CRAWLER DRIVE ALWAYS IN RABBIT MODE. IT DOESNOT BE SWITCHED TO TURTLE MODE. / 左クローラのみ常にうさぎモード。低速にならない。	

ATTACHMENT	—
------------	---

REMARK	WITH EXTRA BUCKET / 追加バケットあり
--------	------------------------------

UNDERCARRIAGE	SHOE	TYPE	STEEL
	<input checked="" type="checkbox"/> W/PAD		
	400 mm	OK	
	PIN BUSH	OK	
	CARRIER ROLLER	OK	
	TRACK ROLLER	OK	
	FRONT IDLER	OK	
	SPROCKET	OK	
NOTE			

CAB/CNP	CAB/CNP	CABIN DAMAGED / キャビン割れ、損傷あり
	ROPS	NO / なし
	SEAT	OK
	CONTROL LEVER	OK
	A/C OR HEATER	OK
	COMPUTER	—
	MONITOR	—
	BATTERY	OK
NOTE	DENT COVERS / カバーへこみ	

ATTENTION/注意 *For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
 *別途修理、洗車の費用がかかる場合があります。ご了承くださいますようお願いいたします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
 *Starting from 1st August 2017,for each successful bid a "Successful Bid Fee" will be charged
 *2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました