



GREEN AUCTION

LotNo	2259005	LOCATION	YOKOHAMA-E*
-------	---------	----------	-------------

EXCAVATOR

159th Tender Auction 2026/03/26 ~ 2026/03/27

MAKER	HITACHI	YEAR	2023
MODEL	ZX120-7	HOUR	59
S/N	98879		

 DOCUMENT/書類
 UNABLE TO TRAVEL(START)/不働車

ENGINE	MODEL	TOYOTA 1KD	
	S/N		
	COOLANT	OK	
	OIL	OK	
	START	OK	
	BLOW-BY	NO/なし	
	NOISE	NO/なし	
	EPA	NO/なし	
	NOTE		

FRONT ATTACHMENT	BOOM	TYPE	STD
		OK	
	ARM	TYPE	STD
		OK	
	PIPING	OK 5 PIPIN	
	BUCKET	TYPE	STD
		OK	
	BLADE	-	
	PINS	BOOM	OK
		ARM	OK
BUCKET		OK	
NOTE			

CYLINDERS	BOOM	OK
	SWING	OK
	ARM	OK
	BUCKET	OK
	BLADE	-
	NOTE	

TURN TABLE	OK
------------	----

CONTROL	HYDRAULIC PUMP	OK
	TRAVEL	OK
	SWING	OK
	CONTROL	OK
	NOTE	

ATTACHMENT	-
------------	---

REMARK

REAR CAMERA DENT, BODY PUNCHED S/N UNKNOWN. NEED WASHING. バックカメラへこみ 刻印不明 要洗車

UNDERCARRIAGE	SHOE	TYPE	STEEL
	<input type="checkbox"/> W/PAD	OK	
	<input type="checkbox"/> mm		
	PIN BUSH	OK	
	CARRIER ROLLER	OK	
	TRACK ROLLER	OK	
	FRONT IDLER	OK	
	SPROCKET	OK	
	NOTE		

CAB/CNP	CAB/CNP	OK
	ROPS	YES/あり
	SEAT	OK
	CONTROL LEVER	OK
	A/C OR HEATER	OK
	COMPUTER	OK
	MONITOR	OK
	BATTERY	OK
	NOTE	

ATTENTION/注意

*For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
 *別途修理、洗車の費用がかかる場合があります。ご了承くださいませうお願いします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
 *Starting from 1st August 2017,for each successful bid a " Successful Bid Fee" will be charged
 *2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました