



|       |         |          |            |
|-------|---------|----------|------------|
| LotNo | 1260016 | LOCATION | YOKOHAMA-E |
| MAKER | KUBOTA  | YEAR     | 2015       |
| MODEL | RX-306  | HOOR     | 4564       |
| S/N   | 16624   |          |            |

DOCUMENT/書類     UNABLE TO TRAVEL(START)/不働車

|        |         |         |
|--------|---------|---------|
| ENGINE | MODEL   | D1703   |
|        | S/N     | 7FM7368 |
|        | COOLANT | OK      |
|        | OIL     | OK      |
|        | START   | OK      |
|        | BLOW-BY | NO / なし |
|        | NOISE   | NO / なし |
|        | EPA     | -       |
|        | NOTE    |         |

|                  |                   |      |         |
|------------------|-------------------|------|---------|
| FRONT ATTACHMENT | BOOM              | TYPE | OFF-SET |
|                  |                   |      | OK      |
|                  | ARM               | TYPE | STD     |
|                  |                   |      | OK      |
|                  | PIPING            |      | -       |
|                  | BUCKET            | TYPE | STD     |
|                  |                   |      | OK      |
|                  | BLADE             |      | OK      |
|                  | PINS              | BOOM | OK      |
|                  |                   | ARM  | OK      |
|                  | BUCKET            | OK   |         |
| NOTE             | ARM CRANE/アームクレーン |      |         |

|           |        |    |
|-----------|--------|----|
| CYLINDERS | BOOM   | OK |
|           | SWING  | -  |
|           | ARM    | OK |
|           | BUCKET | OK |
|           | BLADE  | OK |
|           | NOTE   |    |

|            |    |
|------------|----|
| TURN TABLE | OK |
|------------|----|

|               |  |      |        |
|---------------|--|------|--------|
| UNDERCARRIAGE | SHOE                                       | TYPE | RUBBER |
|               | <input type="checkbox"/> W/PAD             |      |        |
|               | <input checked="" type="checkbox"/> 300 mm |      | OK     |
|               | PIN BUSH                                   |      | -      |
|               | CARRIER ROLLER                             |      | OK     |
|               | TRACK ROLLER                               |      | OK     |
|               | FRONT IDLER                                |      | OK     |
|               | SPROCKET                                   |      | OK     |
|               | NOTE                                       |      |        |

|         |               |         |
|---------|---------------|---------|
| CAB/CNP | CAB/CNP       | OK      |
|         | ROPS          | NO / なし |
|         | SEAT          | OK      |
|         | CONTROL LEVER | OK      |
|         | A/C OR HEATER | -       |
|         | COMPUTER      | OK      |
|         | MONITOR       | OK      |
|         | BATTERY       | OK      |
|         | NOTE          |         |

|         |                |   |
|---------|----------------|---|
| CONTROL | HYDRAULIC PUMP | OK  |
|         | TRAVEL         | OK  |
|         | SWING          | -   |
|         | CONTROL        | OK  |
|         | NOTE           | 3WAY MULTI LEVER/3WAYマルチレバー<br>MINOR OIL LEAKING FROM CONTROL VALVE/コントロールバルブから油にじみ |

|            |   |
|------------|---|
| ATTACHMENT | - |
|------------|---|

REMARK

ATTENTION/注意 \*For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.  
 \*別途修理、洗車の費用がかかる場合があります。ご了承くださいませようお願いします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。  
 \*Starting from 1st August 2017,for each successful bid a "Successful Bid Fee" will be charged  
 \*2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました