



GREEN AUCTION

LotNo	1260008	LOCATION	HAKATA-S
-------	---------	----------	----------

MINI EXCAVATOR

160th Tender Auction 2026/04/23 ~ 2026/04/24

MAKER	KUBOTA	YEAR	2016
MODEL	U-20-3S	HOUR	2443
S/N	18633		

 DOCUMENT/書類
 UNABLE TO TRAVEL(START)/不働車

ENGINE	MODEL	D1105
	S/N	1GA2584
	COOLANT	OK
	OIL	OK
	START	OK
	BLOW-BY	YES/あり(SLIGHTLY/小)
	NOISE	NO/なし
	EPA	NO/なし
	NOTE	

FRONT ATTACHMENT	BOOM	TYPE	STD
			OK
	ARM	TYPE	STD
			OK
	PIPING		-
	BUCKET	TYPE	STD
			OK
	BLADE		OK
	PINS	BOOM	LOOSE/ガタ
		ARM	LOOSE/ガタ
	BUCKET	LOOSE/ガタ	
NOTE			

CYLINDERS	BOOM	OK
	SWING	OK
	ARM	MINOR OIL LEAK / 油にじみ
	BUCKET	OK
	BLADE	OK
	NOTE	

TURN TABLE	OK
------------	----

CONTROL	HYDRAULIC PUMP	OK
	TRAVEL	OK
	SWING	OK
	CONTROL	OK
	NOTE	

ATTACHMENT	-
------------	---

REMARK

COVER DENT, RUSTY, SCRATCHED. NEED WASHING FOR SHIPPING ON BULK CARRIER SHIP. カバーへこみ サビ傷 在来船輸出の場合は要洗車カバー

UNDERCARRIAGE	SHOE	TYPE	STEEL,RUBBER
	<input type="checkbox"/> W/PAD		OK
	250 mm		
	PIN BUSH		OK
	CARRIER ROLLER		OK
	TRACK ROLLER		OK
	FRONT IDLER		LOOSE/ガタ(RIGHT SIDE)
	SPROCKET		OK
	NOTE		SHOE TYPE L:RUBBER, R: W/PAD シュー左右タイプ違う

CAB/CNP	CAB/CNP	OK
	ROPS	NO/なし
	SEAT	OK
	CONTROL LEVER	OK
	A/C OR HEATER	-
	COMPUTER	-
	MONITOR	OK
	BATTERY	OK
	NOTE	W/MULTI LEVER

ATTENTION/注意

*For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
 *別途修理、洗車の費用がかかる場合があります。ご了承くださいませようお願いします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
 *Starting from 1st August 2017,for each successful bid a " Successful Bid Fee" will be charged
 *2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました