



LotNo	8140001	LOCATION	KOBE-N
-------	---------	----------	--------

MAKER	AICHI	YEAR	2008				
MODEL	RM04B	HR	9974	CARRIER HR	—	CARRIER KM	—
S/N	719354	CASSIS MODEL	—	CASSIS S/N	—		

DOCUMENT/書類 UNABLE TO TRAVEL(START)/不働車

ENGINE	CARRIER	CRANE	HYDRAULIC (CRANE)	PUMP	OK	TYPE OF OUTRIGGER	—	
	MODEL	—		MAIN WINCH	—	OUTRIGGER CYLINDER	—	
	S/N	—		AUX WINCH	—	OUTRIGGER EXTENSION	—	
	COOLANT	—		BOOM EXTENSION	OK	SWING	—	
	OIL	—		BOOM HOIST	—	CONTROL LEVER	NOTE	
	START	—		NOTE	THE UP/DOWN SWITCH ON THE TOP CONTROL PANEL IS BROKEN, BUT EVERYTHING ELSE WORKS FINE. / 上部操作盤の上下スイッチが不能。その他は動作することを確認済み。			
	BLOW-BY	—						
	NOISE	—						
	NOTE							

ELECTRICAL	LIGHT	—
	WIPER	—
	HEATER	—
	A/C	—
	BATTERY	OK
	NOTE	BATTERY CHARGER NOT VERIFIED / 充電器未確認

HOOK	CAPACITY	MAIN	— (t)	SUB	— (t)
	NO. OF HOOK	— pcs			
	WIRE ROPE	—			
	NOTE				

BOOM	LENGTH	MAX FLOOR HEIGHT 3.8	m
	CONDITION	—	
	SHEEVE	—	
	NOTE		

FORK LIFT	HYDRAULIC	TYPE	—	
		FORK	LENGTH	— mm
			MAST	LENGTH
	HYDRAULIC	LIFT CYLINDER	—	
		TILT CYLINDER	—	
		HOIST CYLINDER	—	
NOTE				

UNDERCARRIAGE	TIRE	SIZE	—	
		CONDITION	—	
	SHOE	<input type="checkbox"/> W/PAD	TYPE	RUBBER
		150 mm	OK	
	PIN BUSH	—		
	CARRIER ROLLER	—		
	TRACK ROLLER	OK		
	FRONT IDLER	OK		
SPROCKET	OK			
NOTE				

TRANSMISSION	NO. OF SPEED	F	—	R	—
	SHIFT	—			
	OIL	—			
	NOTE				

JIB	NO. OF SEC	—	sec
	CONDITON	—	
	NOTE		

CAB	—
SEAT	—
NOTE	

SAFETY DEVICE	MONITOR	OK
	AML	—
	OVER WIND CUT	—
	NOTE	

BRAKE	FOOT	—
	PARKING	—
	NOTE	

REMARK	THE TOP CONTROL PANEL CASE IS BROKEN. / 上部操作盤のケースが破損
--------	--

ATTENTION/ 注意 *For unit required washing or repair, extra fee will be charge. The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
 *別途修理、洗車の費用がかかる場合があります。ご了承くださいませようお願いします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
 *Starting from 1st August 2017, for each successful bid a "Successful Bid Fee" will be charged
 *2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました