



| | | | |
|-------|---------|----------|--------|
| LotNo | 8140004 | LOCATION | KOBE-N |
|-------|---------|----------|--------|

| | | | | | | | |
|-------|--------|--------------|------|------------|---|------------|---|
| MAKER | AICHI | YEAR | 2013 | | | | |
| MODEL | SV04B | HOUR | 5988 | CARRIER HR | — | CARRIER KM | — |
| S/N | 743087 | CASSIS MODEL | — | CASSIS S/N | — | | |

DOCUMENT/書類 UNABLE TO TRAVEL(START)/不動車

| | | | | | | | | |
|--------|---------|-------|-------------------|----------------|----|---------------------|----|--|
| ENGINE | CARRIER | CRANE | HYDRAULIC (CRANE) | PUMP | OK | TYPE OF OUTRIGGER | — | |
| | MODEL | — | | MAIN WINCH | — | OUTRIGGER CYLINDER | — | |
| | S/N | — | | AUX WINCH | — | OUTRIGGER EXTENSION | — | |
| | COOLANT | — | | BOOM EXTENSION | OK | SWING | — | |
| | OIL | — | | BOOM HOIST | — | CONTROL LEVER | OK | |
| | START | — | | NOTE | | | | |
| | BLOW-BY | — | | | | | | |
| | NOISE | — | | | | | | |
| | NOTE | | | | | | | |

| | | |
|------------|---------|---------------------------------------|
| ELECTRICAL | LIGHT | — |
| | WIPER | — |
| | HEATER | — |
| | A/C | — |
| | BATTERY | OK |
| | NOTE | BATTERY CHARGER NOT VERIFIED / 充電器未確認 |

| | | | | | |
|------|-------------|-------|-------|-----|-------|
| HOOK | CAPACITY | MAIN | — (t) | SUB | — (t) |
| | NO. OF HOOK | — pcs | | | |
| | WIRE ROPE | — | | | |
| | NOTE | | | | |

| | | | |
|------|-----------|----------------------|---|
| BOOM | LENGTH | MAX FLOOR HEIGHT 3.8 | m |
| | CONDITION | — | |
| | SHEEVE | — | |
| | NOTE | | |

| | | | | |
|-----------|-----------|----------------|--------|------|
| FORK LIFT | HYDRAULIC | TYPE | — | |
| | | FORK | LENGTH | — mm |
| | | | — | |
| | | MAST | LENGTH | — mm |
| | — | | | |
| | HYDRAULIC | LIFT CYLINDER | — | |
| | | TILT CYLINDER | — | |
| | | HOIST CYLINDER | — | |
| NOTE | | | | |

| | | | |
|----------------|-----------|----|--|
| TIRE | SIZE | — | |
| | CONDITION | OK | |
| SHOE | W/PAD | — | |
| | — mm | — | |
| PIN BUSH | — | | |
| CARRIER ROLLER | — | | |
| TRACK ROLLER | — | | |
| FRONT IDLER | — | | |
| SPROCKET | — | | |
| NOTE | | | |

| | | | | | |
|--------------|--------------|---|---|---|---|
| TRANSMISSION | NO. OF SPEED | F | — | R | — |
| | SHIFT | — | | | |
| | OIL | — | | | |
| | NOTE | | | | |

| | | | |
|-----|------------|---|-----|
| JIB | NO. OF SEC | — | sec |
| | CONDITON | — | |
| | NOTE | | |

| | |
|------|---|
| CAB | — |
| SEAT | — |
| NOTE | |

| | | |
|---------------|---------------|----|
| SAFETY DEVICE | MONITOR | OK |
| | AML | — |
| | OVER WIND CUT | — |
| | NOTE | |

| | | |
|-------|---------|---|
| BRAKE | FOOT | — |
| | PARKING | — |
| | NOTE | |

| | |
|--------|--|
| REMARK | |
|--------|--|

ATTENTION/ 注意 *For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
 *別途修理、洗車の費用がかかる場合があります。ご了承くださいませようお願いします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
 *Starting from 1st August 2017,for each successful bid a "Successful Bid Fee" will be charged
 *2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました