



GREEN AUCTION

| | | | |
|-------|---------|----------|----------|
| LotNo | 2140003 | LOCATION | HAKATA-A |
|-------|---------|----------|----------|

EXCAVATOR

140th Internet Auction 2026/05/21 ~ 2026/05/22

| | | | |
|-------|-----------|------|------|
| MAKER | KOMATSU | YEAR | 2007 |
| MODEL | PC128US-8 | HOUR | 8829 |
| S/N | 20492 | | |

 DOCUMENT/書類
 UNABLE TO TRAVEL(START)/不働車

| | | |
|--------|---------|-----------------------------------|
| ENGINE | MODEL | UNKNOWN |
| | S/N | UNKNOWN |
| | COOLANT | OK |
| | OIL | OK |
| | START | OK |
| | BLOW-BY | NO/なし |
| | NOISE | NO/なし |
| | EPA | NO/なし |
| | NOTE | IDLE SPEED IS UNATABLE. アイドリング不安定 |

| | | | |
|------------------|--------|------|-----|
| FRONT ATTACHMENT | BOOM | TYPE | STD |
| | | OK | |
| | ARM | TYPE | STD |
| | | OK | |
| | PIPING | OK | |
| | BUCKET | TYPE | STD |
| | | OK | |
| | BLADE | - | |
| | PINS | BOOM | OK |
| | | ARM | OK |
| | BUCKET | OK | |
| NOTE | | | |

| | | |
|-----------|--------|------------------------------|
| CYLINDERS | BOOM | OIL LEAKING /油漏れ(BOTH SIDES) |
| | SWING | - |
| | ARM | OK |
| | BUCKET | OK |
| | BLADE | - |
| | NOTE | |

| | |
|------------|----|
| TURN TABLE | OK |
|------------|----|

| | | |
|---------|----------------|----|
| CONTROL | HYDRAULIC PUMP | OK |
| | TRAVEL | OK |
| | SWING | OK |
| | CONTROL | OK |
| | NOTE | |

| | |
|------------|---|
| ATTACHMENT | - |
|------------|---|

REMARK

WASHING REQUIRED. BODY MARKING IS UNCLEAR. 要洗車
刻印不鮮明

| | | | |
|---------------|--------------------------------|------------------------|-------|
| UNDERCARRIAGE | SHOE | TYPE | STEEL |
| | <input type="checkbox"/> W/PAD | SHOE PAD IS WORN.パット摩耗 | |
| | 500 mm | | |
| | PIN BUSH | OK | |
| | CARRIER ROLLER | OK | |
| | TRACK ROLLER | OK | |
| | FRONT IDLER | OK | |
| | SPROCKET | OK | |
| | NOTE | | |

| | | |
|---------|---------------|----------|
| CAB/CNP | CAB/CNP | OK |
| | ROPS | NO/なし |
| | SEAT | TORN/破れ |
| | CONTROL LEVER | OK |
| | A/C OR HEATER | - |
| | COMPUTER | OK |
| | MONITOR | OK |
| | BATTERY | DEAD/あがり |
| | NOTE | |

ATTENTION/注意

*For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
 *別途修理、洗車の費用がかかる場合があります。ご了承くださいませようお願いします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
 *Starting from 1st August 2017,for each successful bid a " Successful Bid Fee" will be charged
 *2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました