



GREEN AUCTION

LotNo	5140001	LOCATION	HAKATA-S
-------	---------	----------	----------

CRANE

140th Internet Auction 2026/05/21 ~ 2026/05/22

MAKER	KATO	YEAR	2006	CARRIER HR		CARRIER KM	
MODEL	KRM-13H	HOUR	2374	CHASSIS S/N			
S/N	5911143	CHASSIS MODEL					

 DOCUMENT/書類
 UNABLE TO TRAVEL(START)/不働車

ENGINE	CARRIER	CRANE	HYDRAULIC (CRANE)	PUMP	-	TYPE OF OUTRIGGER	H-TYPE
	MODEL	-		MAIN WINCH	-	OUTRIGGER CYLINDER	-
	S/N	-		AUX WINCH	-	OUTRIGGER EXTENSION	-
	COOLANT	OK		BOOM EXTENSION	-	SWING	-
	OIL	OK		BOOM HOIST	-	CONTROL LEVER	-
	START	OK		NOTE			
	BLOW-BY	YES/あり(SEVERELY/大)					
	NOISE	NO/なし					
	NOTE						

ELECTRICAL	LIGHT	OK
	WIPER	-
	HEATER	-
	A/C	OK
	BATTERY	OK
	NOTE	

HOOK	CAPACITY	MAIN	-	(t)	SPS	-	(t)	
	NO. OF HOOK							pcs
	WIRE LOUPE							
	NOTE							

BOOM	LENGTH	-	m
	CONDITION		
	SHEEVE		
	NOTE		

TRANSMISSION	NO. OF SPEED	F	-	R	-
	SHIFT	OK			
	OIL	-			
	NOTE				

JIB	NO. OF SEC	-	sec
	CONDITION		
	NOTE		

SAFETY DEVICE	MONITOR	OK
	AML	-
	OVER WIND CUT	-
NOTE		

FORK LIFT	TYPE	-	
	FORK	LENGTH	- mm
	MAST	LENGTH	- mm
HYDRAULIC	LIFT CYLINDER	-	
	TILT CYLINDER	-	
	HOIST CYLINDER	-	
	NOTE		

BRAKE	FOOT	OK
	PARKING	OK
	NOTE	

TIRE	SIZE	275/80R22.5	
	CONDITION	OK	
UNDERCARRIAGE	SHOE	TYPE	-
	<input type="checkbox"/> W/PAD		
	<input type="checkbox"/> mm		
	PIN BUSH	-	
	CARRIER ROLLER	-	
	TRACK ROLLER	-	
	FRONT IDLER	-	
SPROCKET	-		
NOTE			

REMARK	CRANE WORKING NOT TESTED. クレーン動作未確認
--------	-------------------------------------

ATTENTION/注意

*For unit required washing or repair, extra fee will be charge. The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
 *別途修理、洗車の費用がかかる場合があります。ご了承くださいませ。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
 *Starting from 1st August 2017, for each successful bid a "Successful Bid Fee" will be charged