



LotNo	9140017	LOCATION	HAKATA-S
MAKER	DENYO	YEAR	2017
MODEL	DLW-400LSWE	HOUR	1852
S/N	5803806	MILE	

DOCUMENT/書類 UNABLE TO TRAVEL(START)/不働車

MODEL	-
S/N	-
COOLANT	OK
OIL	OK
START	OK
BLOW-BY	YES/あり(SLIGHTLY/小)
NOISE	NO/なし
EPA	NO/なし
NOTE	ENGINE MINOR OIL LEAKING. エンジン油にじみ箇所あり

RATED POWER	-	KVA
RATED AMPERE	-	A
TERMINAL	OK	
CIRCUIT BREAKER	OK	
INSLATION	-	MΩ
NOTE	WELDING NOR TESTED. 溶接未確認	

RATED PRESS	-	Kgf/m ² Mpa	RATED AIR	-	m ³ /min
AIR VALVE	-				
SAFTY VALVE	-				
UNLOAD	-				
OIL	-				
NOTE					

LIGHTS	-
MONITOR	OK
SWITCH	OK
BATTERY	OK
NOTE	

BLANK	
-------	--

PUMP	-
HOPPER CYLINDER	-
PIVOT CYLINDER	-
SCREED CYLINDER (UP DOWN)	-
SCREED CYLINDER (EXPENDABLE)	-
CONTROL VALVE	-
NOTE	

CAB/GNP	-
SEAT	-
NOTE	

IRON	WIDTH	-	m
EXTENSION IRON	WIDTH	-	m
SCREW(SUB)	-		
NOTE			

TIRE	SIZE	F	-	R	-
SHOE	WIDTH	- mm			
PIN BUSH	-				
CARRIER ROLLER	-				
TRACK ROLLER	-				
FRONT IDLER	-				
SPROCKETS	-				
NOTE					

FINISHER	
----------	--

REMARK	
--------	--

OTHER ITEMS				NOTE
-	-	-	-	
-	-	-	-	
-	-	-	-	

ATTENTION/注意

*For unit required washing or repair, extra fee will be charge. The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
 *別途修理、洗車の費用がかかる場合があります。ご了承くださいますようお願いいたします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
 *Starting from 1st August 2017, for each successful bid a " Successful Bid Fee " will be charged
 *2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました