



LotNo	8141001	LOCATION	KOBE-N*
-------	---------	----------	---------

MAKER	AICHI	YEAR	2007				
MODEL	SR21A	HOUR	5011	CARRIER HR	—	CARRIER KM	—
S/N	714731	CASSIS MODEL	—	CASSIS S/N	—		

DOCUMENT/書類 UNABLE TO TRAVEL(START)/不働車

ENGINE	CARRIER	CRANE	HYDRAULIC (CRANE)	PUMP	RUSTY / サビ	TYPE OF OUTRIGGER	—	
	MODEL	4JG1		—	MAIN WINCH	—	OUTRIGGER CYLINDER	—
	S/N	344489		—	AUX WINCH	—	OUTRIGGER EXTENSION	—
	COOLANT	OK		—	BOOM EXTENSION	OK	SWING	OK
	OIL	OK		—	BOOM HOIST	OK	CONTROL LEVER	OK
	START	OK		—	NOTE	THE SAFETY PEDAL IS A BIT STUCK/セーフティペダル固着気味		
	BLOW-BY	NO / なし		—				
	NOISE	NO / なし		—				
	NOTE							

ELECTRICAL	LIGHT	—
	WIPER	—
	HEATER	—
	A/C	—
	BATTERY	OK
	NOTE	

HOOK	CAPACITY	MAIN	— (t)	SUB	— (t)
	NO. OF HOOK		—		pcs
	WIRE ROPE		—		
	NOTE				

BOOM	LENGTH	21	m
	CONDITION	OK	
	SHEEVE	OK	
	NOTE		

FORK LIFT	HYDRAULIC	TYPE	—
		FORK	LENGTH — mm
		MAST	LENGTH — mm
		LIFT CYLINDER	—
	TILT CYLINDER	—	
	HOIST CYLINDER	—	
	NOTE		

TIRE	SIZE	—	
	CONDITION	—	
UNDERCARRIAGE	SHOE	TYPE	STEEL
	<input checked="" type="checkbox"/> W/PAD		
	500 mm	OK	
	PIN BUSH	OK	
	CARRIER ROLLER	OK	
	TRACK ROLLER	OK	
	FRONT IDLER	OK	
	SPROCKET	OK	
NOTE	THERE ARE KINKS IN BOTH CRAWLER TRACKS/両側のクローラーにキックあり		

TRANSMISSION	NO. OF SPEED	F	1	R	1
	SHIFT	OK			
	OIL	OK			
	NOTE				

JIB	NO. OF SEC	—	sec
	CONDITON	—	
	NOTE		

CAB	—
SEAT	—
NOTE	

SAFETY DEVICE	MONITOR	OK
	AML	—
	OVER WIND CUT	—
	NOTE	

BRAKE	FOOT	OK
	PARKING	—
	NOTE	

REMARK	*PUNCHED NO. UNKNOWN (刻印不明)
--------	-----------------------------

ATTENTION/ 注意 *For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
 *別途修理、洗車の費用がかかる場合があります。ご了承くださいませようお願いします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
 *Starting from 1st August 2017,for each successful bid a "Successful Bid Fee" will be charged
 *2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました