



LotNo	1141002	LOCATION	YOKOHAMA-E*
MAKER	YANMAR	YEAR	-
MODEL	09JUST(J09-A)	HOUR	1353
S/N	02215B		

DOCUMENT/書類 UNABLE TO TRAVEL(START)/不働車

ENGINE	MODEL	2TE67L-BV3	
	S/N	09729	
	COOLANT	OK	
	OIL	OK	
	START	OK	
	BLOW-BY	NO / なし	
	NOISE	NO / なし	
	EPA	YES / あり	
	NOTE		

FRONT ATTACHMENT	BOOM	TYPE	OFFSET
		OK	
	ARM	TYPE	STD
		OK	
	PIPING	-	
	BUCKET	TYPE	STD
		OK	
	BLADE	OK	
	PINS	BOOM	OK
		ARM	OK
BUCKET		OK	
NOTE			

CYLINDERS	BOOM	OK
	SWING	OK
	ARM	OK
	BUCKET	OK
	BLADE	OK
	NOTE	

TURN TABLE	OK
------------	----

CONTROL	HYDRAULIC PUMP	OK
	TRAVEL	OK
	SWING	OK
	CONTROL	OK
NOTE		

ATTACHMENT	-
------------	---

UNDERCARRIAGE	SHOE	TYPE	RUBBER
	<input type="checkbox"/> W/PAD	OK	
	180 mm		
	PIN BUSH	OK	
	CARRIER ROLLER	OK	
	TRACK ROLLER	OK	
	FRONT IDLER	OK	
	SPROCKET	OK	
NOTE			

CAB/CNP	CAB/CNP	
	ROPS	NO / なし
	SEAT	OK
	CONTROL LEVER	OK
	A/C OR HEATER	
	COMPUTER	
	MONITOR	
	BATTERY	WEAK / 弱い
NOTE		

REMARK
SERIAL PLATE MISSSING. / シリアルプレート欠損 *PUNCHED NO. UNCLEAR (刻印不鮮明)

ATTENTION/注意 *For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
 *別途修理、洗車の費用がかかる場合があります。ご了承くださいませようお願いします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
 *Starting from 1st August 2017,for each successful bid a "Successful Bid Fee" will be charged
 *2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました