



LotNo	8261025	LOCATION	KOBE-N
-------	---------	----------	--------

MAKER	AICHI	YEAR	2012				
MODEL	SV10CWL	HOUR	776	CARRIER HR	—	CARRIER KM	—
S/N	737364	CASSIS MODEL	—	CASSIS S/N	—		

DOCUMENT/書類 UNABLE TO TRAVEL(START)/不働車

ENGINE	CARRIER	CRANE	HYDRAULIC (CRANE)	PUMP	—	TYPE OF OUTRIGGER	—	
	MODEL	—		MAIN WINCH	—	OUTRIGGER CYLINDER	—	
	S/N	—		AUX WINCH	—	OUTRIGGER EXTENSION	—	
	COOLANT	—		BOOM EXTENSION	—	SWING	—	
	OIL	—		BOOM HOIST	—	CONTROL LEVER	—	
	START	—		NOTE	TILT LIGHT FLASHING. ONLY STEERING WORKS. NO TRAVEL & LIFT. / 傾斜警告灯が点滅。操舵のみ操作可。前後進&リフトは動作しない。			
	BLOW-BY	—						
	NOISE	—						
	NOTE							

ELECTRICAL	LIGHT	—
	WIPER	—
	HEATER	—
	A/C	—
	BATTERY	OK
	NOTE	

HOOK	CAPACITY	MAIN	— (t)	SUB	— (t)
	NO. OF HOOK		—		pcs
	WIRE ROPE		—		
	NOTE				

BOOM	LENGTH	—	m
	CONDITION	—	
	SHEEVE	—	
	NOTE		

FORK LIFT	HYDRAULIC	TYPE	—
		FORK	LENGTH — mm
		MAST	LENGTH — mm
		LIFT CYLINDER	—
	TILT CYLINDER	—	
	HOIST CYLINDER	—	
	NOTE		

UNDERCARRIAGE	TIRE	SIZE	—
		CONDITION	OK
	SHOE	TYPE	—
		W/PAD	— mm
	PIN BUSH		—
	CARRIER ROLLER		—
	TRACK ROLLER		—
	FRONT IDLER		—
SPROCKET		—	
NOTE			

TRANSMISSION	NO. OF SPEED	F	—	R	—
	SHIFT		—		
	OIL		—		
	NOTE				

JIB	NO. OF SEC	—	sec
	CONDITON	—	
	NOTE		

CAB	—
SEAT	—
NOTE	

SAFETY DEVICE	MONITOR	OK
	AML	—
	OVER WIND CUT	—
	NOTE	

BRAKE	FOOT	—
	PARKING	—
	NOTE	

REMARK	MAX FLOOR HEIGHT : 9.6M UNABLE TO TRAVEL / 走行不働
--------	--

ATTENTION/ 注意 *For unit required washing or repair, extra fee will be charge. The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
 *別途修理、洗車の費用がかかる場合があります。ご了承くださいませようお願いします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
 *Starting from 1st August 2017, for each successful bid a "Successful Bid Fee" will be charged
 *2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました