



GREEN AUCTION

LotNo	1261013	LOCATION	HAKATA-S
-------	---------	----------	----------

MINI EXCAVATOR

161th Tender Auction 2026/06/18 ~ 2026/06/19

MAKER	HITACHI	YEAR	2013
MODEL	ZX40U-5A	HOUR	-
S/N	30960		

 DOCUMENT/書類
 UNABLE TO TRAVEL(START)/不働車

ENGINE	MODEL	4TNV88-ZPHB	
	S/N	P1275	
	COOLANT	OK	
	OIL	OK	
	START	OK	
	BLOW-BY	YES/あり(SLIGHTLY/小)	
	NOISE	NO/なし	
	EPA	NO/なし	
	NOTE		

FRONT ATTACHMENT	BOOM	TYPE	SWING
		OK	
	ARM	TYPE	STD
		OK REINFORCED/補強あり	
	PIPING	OK	
	BUCKET	TYPE	STD
		OK	
	BLADE	DENT/へこみ	
	PINS	BOOM	LOOSE/ガタ
		ARM	LOOSE/ガタ
BUCKET		LOOSE/ガタ(SEVERELY/大きい)	
NOTE			

CYLINDERS	BOOM	OK
	SWING	OK
	ARM	ROD SCRATCHED/ロッド傷あり
	BUCKET	OIL SEEPAGE /油にじみ
	BLADE	OK
	NOTE	

TURN TABLE	OK
------------	----

CONTROL	HYDRAULIC PUMP	OK
	TRAVEL	OK
	SWING	OK
	CONTROL	OK
	NOTE	

ATTACHMENT	-
------------	---

REMARK	W/ MULTI LEVER
--------	----------------

UNDERCARRIAGE	SHOE	TYPE	STEEL
	<input checked="" type="checkbox"/> W/PAD	OK	
	400 mm		
	PIN BUSH	OK	
	CARRIER ROLLER	OK	
	TRACK ROLLER	OK	
	FRONT IDLER	OK	
	SPROCKET	OK	
	NOTE	SHOE LINK PLAY. シューリンク ガタ DIRTY, REQUIRES CLEANING. 汚れあり 要洗車	

CAB/CNP	CAB/CNP	ROOF DENTED. ルーフへこみ
	ROPS	NO/なし
	SEAT	TORN/破れ
	CONTROL LEVER	OK
	A/C OR HEATER	-
	COMPUTER	NG
	MONITOR	NG
	BATTERY	OK
	NOTE	

ATTENTION/注意

*For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
 *別途修理、洗車の費用がかかる場合があります。ご了承くださいませようお願いします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
 *Starting from 1st August 2017,for each successful bid a " Successful Bid Fee" will be charged
 *2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました