



GREEN AUCTION

LotNo	2261002	LOCATION	HAKATA-S
-------	---------	----------	----------

EXCAVATOR

161th Tender Auction 2026/06/18 ~ 2026/06/19

MAKER	KOBELCO	YEAR	2014
MODEL	SK80UR-6	HOUR	5293
S/N	YR10-10194		

 DOCUMENT/書類
 UNABLE TO TRAVEL(START)/不働車

ENGINE	MODEL	-
	S/N	-
	COOLANT	OK
	OIL	OK
	START	OK
	BLOW-BY	YES/あり(SLIGHTLY/小)
	NOISE	NO/なし
	EPA	NO/なし
	NOTE	OIL SEEPING FROM TAPPET COVER AND FRONT COVER. タペットカバー フロントカバー 油にじみ

FRONT ATTACHMENT	BOOM	TYPE	OFF-SET
			OK
	ARM	TYPE	STD
			OK REINFORCED/補強あり 溶接あり/WELDED
	PIPING		-
	BUCKET	TYPE	STD
			CRACKED/亀裂
	BLADE		OK
	PINS	BOOM	OK
		ARM	OK
	BUCKET	OK	
NOTE			

CYLINDERS	BOOM	OK
	SWING	OK
	ARM	OK
	BUCKET	OK
	BLADE	OK
	NOTE	

TURN TABLE	SIDE PLAY/横ガタ
------------	---------------

CONTROL	HYDRAULIC PUMP	OK
	TRAVEL	OK
	SWING	OK
	CONTROL	OK
	NOTE	

ATTACHMENT	-
------------	---

REMARK	W/ 1.7t LIFTING CRANE. MULTI LEVER
--------	------------------------------------

UNDERCARRIAGE	SHOE	TYPE	STEEL
	<input checked="" type="checkbox"/> W/PAD		OK
	450 mm		
	PIN BUSH		OK
	CARRIER ROLLER		OK
	TRACK ROLLER		OK
	FRONT IDLER		OK
	SPROCKET		OK
	NOTE	SHOE LINK PLAY. シューリンクガタ DIRTY. REQUIRES CLEANING. 汚れあり 要洗車	

CAB/CNP	CAB/CNP	OK
	ROPS	NO/なし
	SEAT	SNAG/破れ
	CONTROL LEVER	OK
	A/C OR HEATER	OK
	COMPUTER	OK
	MONITOR	OK
	BATTERY	OK
	NOTE	

ATTENTION/注意

*For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
 *別途修理、洗車の費用がかかる場合があります。ご了承くださいませうお願いします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
 *Starting from 1st August 2017,for each successful bid a " Successful Bid Fee" will be charged
 *2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました