



LotNo	5142001	LOCATION	KOBE-N
-------	---------	----------	--------

MAKER	MAEDA	YEAR	2006				
MODEL	LC785-6	HOUR	6807	CARRIER HR	—	CARRIER KM	—
S/N	31214	CASSIS MODEL	—	CASSIS S/N	—		

DOCUMENT/書類 UNABLE TO TRAVEL(START)/不働車

ENGINE	CARRIER	CRANE	HYDRAULIC (CRANE)	PUMP	OK	TYPE OF OUTRIGGER	—	
	MODEL	—		MAIN WINCH	OK	OUTRIGGER CYLINDER	—	
	S/N	—		AUX WINCH	—	OUTRIGGER EXTENSION	—	
	COOLANT	OK		BOOM EXTENSION	OK	SWING	OK	
	OIL	OK		BOOM HOIST	OK	CONTROL LEVER	OK	
	START	OK		NOTE	SWIVEL MINOR OIL LEAK, WET / スイベル周辺 オイルにじみ, ベタ			
	BLOW-BY	NO / なし						
	NOISE	NO / なし						
	NOTE	EPA LABEL PRESENT / U.S.EPAあり						

ELECTRICAL	LIGHT	OK
	WIPER	OK
	HEATER	OK
	A/C	OK
	BATTERY	OK
	NOTE	TRAVEL SPEED SWITCH POOR RESPONSE. / パネルスイッチ(走行スピード等)の反応悪い

HOOK	CAPACITY	MAIN	4.9 (t)	SUB	— (t)
	NO. OF HOOK	1 pcs			
	WIRE ROPE	OK			
	NOTE				

BOOM	LENGTH	—	m
	CONDITION	OK	
	SHEEVE	OK	
	NOTE		

FORK LIFT	HYDRAULIC	TYPE	—
		FORK	LENGTH — mm
		MAST	LENGTH — mm
	HYDRAULIC	LIFT CYLINDER	—
		TILT CYLINDER	—
		HOIST CYLINDER	—
NOTE			

TIRE	SIZE	—	
	CONDITION	—	
UNDERCARRIAGE	SHOE	TYPE	STEEL
	<input checked="" type="checkbox"/> W/PAD		
	450 mm	OK	
	PIN BUSH	OK	
	CARRIER ROLLER	OK	
	TRACK ROLLER	OK	
	FRONT IDLER	OK	
	SPROCKET	OK	
NOTE	TRAVEL MOTOR MINOR OIL LEAK / 走行モーター オイルにじみ		

TRANSMISSION	NO. OF SPEED	F	—	R	—
	SHIFT	—			
	OIL	—			
	NOTE				

JIB	NO. OF SEC	—	sec
	CONDITON	—	
	NOTE		

CAB	OK
SEAT	TORN / 破れ (SLIGHT / 小)
NOTE	

SAFETY DEVICE	MONITOR	OK
	AML	OK
	OVER WIND CUT	OK
	NOTE	

BRAKE	FOOT	—
	PARKING	—
	NOTE	

REMARK

ATTENTION/ 注意 *For unit required washing or repair, extra fee will be charge. The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
 *別途修理、洗車の費用がかかる場合があります。ご了承くださいませようお願いします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
 *Starting from 1st August 2017, for each successful bid a "Successful Bid Fee" will be charged
 *2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました