



LotNo	8142002	LOCATION	KOBE-N
-------	---------	----------	--------

MAKER	AICHI	YEAR	2008				
MODEL	RM04B	HOUR	9974	CARRIER HR	—	CARRIER KM	—
S/N	719354	CASSIS MODEL	—	CASSIS S/N	—		

DOCUMENT/書類 UNABLE TO TRAVEL(START)/不働車

ENGINE	CARRIER	CRANE	HYDRAULIC (CRANE)	PUMP	OK	TYPE OF OUTRIGGER	—	
	MODEL	—		MAIN WINCH	—	OUTRIGGER CYLINDER	—	
	S/N	—		AUX WINCH	—	OUTRIGGER EXTENSION	—	
	COOLANT	—		BOOM EXTENSION	OK	SWING	—	
	OIL	—		BOOM HOIST	—	CONTROL LEVER	NOTE	
	START	—		NOTE	THE UP/DOWN SWITCH ON THE TOP CONTROL PANEL IS BROKEN, BUT EVERYTHING ELSE WORKS FINE. / 上部操作盤の上下スイッチが不能。その他は動作することを確認済み。			
	BLOW-BY	—						
	NOISE	—						
	NOTE							

ELECTRICAL	LIGHT	—
	WIPER	—
	HEATER	—
	A/C	—
	BATTERY	OK
NOTE	BATTERY CHARGER NOT VERIFIED / 充電器未確認	

HOOK	CAPACITY	MAIN	— (t)	SUB	— (t)
	NO. OF HOOK	— pcs			
	WIRE ROPE	—			
	NOTE				

BOOM	LENGTH	MAX FLOOR HEIGHT 3.8 m
	CONDITION	—
	SHEEVE	—
	NOTE	

FORK LIFT	HYDRAULIC	TYPE	—
		FORK	LENGTH — mm
		MAST	LENGTH — mm
	LIFT	LIFT CYLINDER	—
		TILT CYLINDER	—
		HOIST CYLINDER	—
NOTE			

TIRE	SIZE	—
	CONDITION	—
UNDERCARRIAGE	SHOE	TYPE RUBBER
	<input type="checkbox"/> W/PAD	
	150 mm	OK
	PIN BUSH	—
	CARRIER ROLLER	—
	TRACK ROLLER	OK
	FRONT IDLER	OK
SPROCKET	OK	
NOTE		

TRANSMISSION	NO. OF SPEED	F	—	R	—
	SHIFT	—			
	OIL	—			
	NOTE				

JIB	NO. OF SEC	— sec
	CONDITON	—
	NOTE	

CAB	—
SEAT	—
NOTE	

SAFETY DEVICE	MONITOR	OK
	AML	—
	OVER WIND CUT	—
	NOTE	

BRAKE	FOOT	—
	PARKING	—
	NOTE	

REMARK	THE TOP CONTROL PANEL CASE IS BROKEN. / 上部操作盤のケースが破損
--------	--

ATTENTION/ 注意 *For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
 *別途修理、洗車の費用がかかる場合があります。ご了承くださいませようお願いします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
 *Starting from 1st August 2017,for each successful bid a "Successful Bid Fee" will be charged
 *2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました