



LotNo	8142003	LOCATION	KOBE-N
-------	---------	----------	--------

MAKER	AICHI	YEAR	2009				
MODEL	RX07B	HOUR	10406	CARRIER HR	—	CARRIER KM	—
S/N	729433	CASSIS MODEL	—	CASSIS S/N	—		

DOCUMENT/書類 UNABLE TO TRAVEL(START)/不働車

ENGINE	CARRIER	CRANE	HYDRAULIC (CRANE)	PUMP	OK	TYPE OF OUTRIGGER	—	
	MODEL	—		MAIN WINCH	—	OUTRIGGER CYLINDER	—	
	S/N	—		AUX WINCH	—	OUTRIGGER EXTENSION	—	
	COOLANT	—		BOOM EXTENSION	OK	SWING	—	
	OIL	—		BOOM HOIST	—	CONTROL LEVER	OK	
	START	—		NOTE	IT TRIES TO LIFT, BUT STOPS HALFWAY DUE TO HIGH FRICTION. NEED MAINTENANCE. / リフトが途中でとまる。摩擦が大きい。要整備			
	BLOW-BY	—						
	NOISE	—						
	NOTE							

ELECTRICAL	LIGHT	—
	WIPER	—
	HEATER	—
	A/C	—
	BATTERY	OK
	NOTE	BATTERY CHARGER NOT VERIFIED / 充電器未確認

HOOK	CAPACITY	MAIN	— (t)	SUB	— (t)
	NO. OF HOOK	— pcs			
	WIRE ROPE	—			
	NOTE				

BOOM	LENGTH	MAX FLOOR HEIGHT 6.7 m
	CONDITION	—
	SHEEVE	—
	NOTE	

FORK LIFT	HYDRAULIC	TYPE	—
		FORK	LENGTH — mm
		MAST	LENGTH — mm
		LIFT CYLINDER	—
	TILT CYLINDER	—	
	HOIST CYLINDER	—	
	NOTE		

UNDERCARRIAGE	TIRE	SIZE	—
		CONDITION	OK
	SHOE	TYPE	RUBBER
		W/PAD	— mm
	PIN BUSH	—	
	CARRIER ROLLER	—	
	TRACK ROLLER	OK	
	FRONT IDLER	OK	
SPROCKET	LEFT, WORN / 摩耗 (左)		
NOTE	WHEN I TURN THE STEERING, THE LEFT SPROCKET SOMETIMES SLIPS. / 舵を切ると左スプロケットが滑ることがある		

TRANSMISSION	NO. OF SPEED	F	—	R	—
	SHIFT	—			
	OIL	—			
	NOTE				

JIB	NO. OF SEC	— sec
	CONDITON	—
	NOTE	

CAB	—
SEAT	—
NOTE	

SAFETY DEVICE	MONITOR	OK
	AML	—
	OVER WIND CUT	—
	NOTE	

BRAKE	FOOT	—
	PARKING	—
	NOTE	

REMARK

HANDRAIL IS DEFECT / 手すり不良

ATTENTION/ 注意 *For unit required washing or repair, extra fee will be charge. The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
 *別途修理、洗車の費用がかかる場合があります。ご了承くださいませようお願いします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
 *Starting from 1st August 2017, for each successful bid a "Successful Bid Fee" will be charged
 *2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました