



LotNo	8142009	LOCATION	KOBE-N
-------	---------	----------	--------

MAKER	GENIE	YEAR	2007				
MODEL	Z-30/20N	HOUR	UNKNOWN	CARRIER HR	—	CARRIER KM	—
S/N	Z30N07-9512	CASSIS MODEL	—	CASSIS S/N	—		

DOCUMENT/書類  UNABLE TO TRAVEL(START)/不働車

ENGINE	CARRIER		CRANE		HYDRAULIC (CRANE)	PUMP	—	TYPE OF OUTRIGGER	—	
	MODEL	—	—	—		MAIN WINCH	—	OUTRIGGER CYLINDER	—	
	S/N	—	—	—		AUX WINCH	—	OUTRIGGER EXTENSION	—	
	COOLANT	—	—	—		BOOM EXTENSION	—	SWING	—	
	OIL	—	—	—		BOOM HOIST	—	CONTROL LEVER	—	
	START	—	—	—		NOTE				
	BLOW-BY	—	—	—						
	NOISE	—	—	—						
	NOTE									

ELECTRICAL	LIGHT	—
	WIPER	—
	HEATER	—
	A/C	—
	BATTERY	DEAD / あがり
NOTE	BATTERY CASE DETACHED. / バッテリーケース外れ	

HOOK	CAPACITY	MAIN	— (t)	SUB	— (t)
	NO. OF HOOK	— pcs			
	WIRE ROPE	—			
	NOTE				

BOOM	LENGTH	—	m
	CONDITION	—	
	SHEEVE	—	
	NOTE		

FORK LIFT	HYDRAULIC	TYPE	—	
		FORK	LENGTH	— mm
			—	
	MAST	LENGTH	— mm	
		—		
		—		
HYDRAULIC	LIFT CYLINDER	—		
	TILT CYLINDER	—		
	HOIST CYLINDER	—		
	NOTE			

TIRE	SIZE	—	
	CONDITION	OK	
SHOE	TYPE	—	
	<input type="checkbox"/> W/PAD	— mm	
PIN BUSH	—		
CARRIER ROLLER	—		
TRACK ROLLER	—		
FRONT IDLER	—		
SPROCKET	—		
NOTE			

TRANSMISSION	NO. OF SPEED	F	—	R	—
	SHIFT	—			
	OIL	—			
	NOTE				

JIB	NO. OF SEC	—	sec
	CONDITON	—	
	NOTE		

CAB	—
SEAT	—
NOTE	HOUR METER UNREADABLE / アワーメーター読めない

SAFETY DEVICE	MONITOR	—
	AML	—
	OVER WIND CUT	—
	NOTE	

BRAKE	FOOT	—
	PARKING	—
	NOTE	

REMARK	REQUIRES REPAIR. OPERATION NOT TESTED. / 修理が必要、動作未確認 FORKLIFT CHARGE REQUIRED FOR RELEASING / 出庫時リフトチャージが必要
--------	--

ATTENTION/ 注意 \*For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.  
 \*別途修理、洗車の費用がかかる場合があります。ご了承くださいませようお願いします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。  
 \*Starting from 1st August 2017,for each successful bid a "Successful Bid Fee" will be charged  
 \*2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました