



GREEN AUCTION

LotNo	2142009	LOCATION	HAKATA-S
-------	---------	----------	----------

EXCAVATOR

142th Internet Auction 2026/07/09 ~ 2026/07/10

MAKER	KOMATSU	YEAR	2013
MODEL	PC120-8	HOUR	5054
S/N	86793		

 DOCUMENT/書類
 UNABLE TO TRAVEL(START)/不働車

ENGINE	MODEL	SAA4D95LE-5	
	S/N	547307	
	COOLANT	OK	
	OIL	OK	
	START	OK	
	BLOW-BY	YES/あり(SLIGHTLY/小)	
	NOISE	NO/なし	
	EPA	NO/なし	
	NOTE		

FRONT ATTACHMENT	BOOM	TYPE	STD
		OK	
	ARM	TYPE	STD
		OK	
	PIPING	-	
	BUCKET	TYPE	STD
		OK	
	BLADE	-	
	PINS	BOOM	LOOSE/
		ARM	LOOSE/ガタ
BUCKET		LOOSE/ガタ	
NOTE			

CYLINDERS	BOOM	OK
	SWING	OK
	ARM	OK
	BUCKET	OK
	BLADE	OK
	NOTE	

TURN TABLE	OK
------------	----

CONTROL	HYDRAULIC PUMP	OK
	TRAVEL	OK
	SWING	OK
	CONTROL	OK
	NOTE	

ATTACHMENT	-
------------	---

REMARK

COVER RUSTY, SCRATCHED. カバー 錆び 傷

UNDERCARRIAGE	SHOE	TYPE	STEEL
	<input checked="" type="checkbox"/> W/PAD	OK	
	500 mm		
	PIN BUSH	OK	
	CARRIER ROLLER	OK	
	TRACK ROLLER	OK	
	FRONT IDLER	OK	
	SPROCKET	OK	
	NOTE	PAD WORN, CRACKED. UNDERCARRIAGE DIRTY. WASHING IS REQUIRED. パッド亀裂 摩耗 足回り汚れ あり 要洗車	

CAB/CNP	CAB/CNP	OK
	ROPS	NO/なし
	SEAT	TORN/破れ
	CONTROL LEVER	OK
	A/C OR HEATER	OK
	COMPUTER	OK
	MONITOR	OK
	BATTERY	OK
	NOTE	

ATTENTION/注意

*For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
 *別途修理、洗車の費用がかかる場合があります。ご了承くださいませうお願いします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
 *Starting from 1st August 2017,for each successful bid a " Successful Bid Fee" will be charged
 *2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました