



LotNo	8142012	LOCATION	KOBE-N
-------	---------	----------	--------

MAKER	JLG	YEAR	2007				
MODEL	E300AJP	HOUR	740	CARRIER HR	—	CARRIER KM	—
S/N	0300114673	CASSIS MODEL	—	CASSIS S/N	—		

DOCUMENT/書類  UNABLE TO TRAVEL(START)/不働車

ENGINE	CARRIER	CRANE	HYDRAULIC (CRANE)	PUMP	OK	TYPE OF OUTRIGGER	—	
	MODEL	—		MAIN WINCH	OK	OUTRIGGER CYLINDER	—	
	S/N	—		AUX WINCH	OK	OUTRIGGER EXTENSION	—	
	COOLANT	—		BOOM EXTENSION	OK	SWING	OK	
	OIL	—		BOOM HOIST	OK	CONTROL LEVER	OK	
	START	—		NOTE				
	BLOW-BY	—						
	NOISE	—						
	NOTE							

ELECTRICAL	LIGHT	—
	WIPER	—
	HEATER	—
	A/C	—
	BATTERY	OK
	NOTE	

HOOK	CAPACITY	MAIN	— (t)	SUB	— (t)
	NO. OF HOOK	— pcs			
	WIRE ROPE	—			
	NOTE				

BOOM	LENGTH	—	m
	CONDITION	—	
	SHEEVE	—	
	NOTE		

FORK LIFT	HYDRAULIC	TYPE	—	
		FORK	LENGTH	— mm
			—	
		MAST	LENGTH	— mm
	—			
	HYDRAULIC	LIFT CYLINDER	—	
		TILT CYLINDER	—	
		HOIST CYLINDER	—	
NOTE				

TIRE	SIZE	—	
	CONDITION	OK	
SHOE	W/PAD	—	
	TYPE	—	
UNDERCARRIAGE	PIN BUSH	—	
	CARRIER ROLLER	—	
	TRACK ROLLER	—	
	FRONT IDLER	—	
	SPROCKET	—	
	NOTE		

TRANSMISSION	NO. OF SPEED	F	—	R	—
	SHIFT	—			
	OIL	—			
	NOTE				

JIB	NO. OF SEC	—	sec
	CONDITON	—	
	NOTE		

CAB	—
SEAT	—
NOTE	

SAFETY DEVICE	MONITOR	OK
	AML	—
	OVER WIND CUT	—
	NOTE	

BRAKE	FOOT	OK
	PARKING	OK
	NOTE	

REMARK

HYDRAULIC LINE (JIB SWING) HOSE PUNCTURED. OTHER FUNCTIONS TESTED OK. / ジブ首振り油圧ホース破れ、その他動作確認済み  
 HYDRAULIC OIL SLIGHTLY LOW / 作動油減り気味

ATTENTION/ 注意

\*For unit required washing or repair, extra fee will be charge. The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.  
 \*別途修理、洗車の費用がかかる場合があります。ご了承くださいませようお願いします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。  
 \*Starting from 1st August 2017, for each successful bid a "Successful Bid Fee" will be charged  
 \*2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました