



GREEN AUCTION

EXCAVATOR

LotNo	2262001	LOCATION	HAKATA-S*
MAKER	KOBELCO	YEAR	1994
MODEL	SK60-2	HOURL	5144
S/N	LE-17788		

☐ DOCUMENT/書類 ☐ UNABLE TO TRAVEL(START)/不動車

ENGINE	MODEL	4JB1
	S/N	—
	COOLANT	OK
	OIL	OK
	START	OK
	BLOW-BY	NO / なし
	NOISE	NO / なし
	EPA	NO / なし
	NOTE	SLIGHT OIL SEEPAGE AT TAPPET COVER / タペットカバー部にじみ FAULTY ENGINE STOP SOLENOID/ストップソレノイド不良 BROKEN ENGINE HOOD DAMPER/エンジンフードダンパー部破損

UNDERCARRIAGE	SHOE	TYPE	STEEL
	☐ W/PAD		
	450 mm	OK	
	PIN BUSH	OK	
	CARRIER ROLLER	WORN / 摩耗	
	TRACK ROLLER	OIL SEEPAGE AT ALL TRACK ROLLERS/全トラックローラーにじみ	
	FRONT IDLER	OK	
	SPROCKET	OK	
	NOTE	OIL LEAK AT RH TRAVEL MOTOR/右走行モーター洩れ	

FRONT ATTACHMENT	BOOM	TYPE	STD
		OK	
	ARM	TYPE	STD
		OK	
	PIPING	—	
	BUCKET	TYPE	STD
		OK	
	BLADE	—	
	PINS	BOOM	OK
		ARM	OK
		BUCKET	OK
	NOTE		

CAB/CNP	BROKEN INTERIOR DOOR HANDLE/内ドアノブ破損
ROPS	NO / なし
SEAT	OK
CONTROL LEVER	BROKEN CONTROL LEVER & OIL LEAK/操作レバー部破損、油洩れ
A/C OR HEATER	MAFUNCTIONING AC SYSTEM/エアコン不良
COMPUTER	OK
MONITOR	OK
BATTERY	OK
NOTE	FAULTY SAFETY LOCK LEVER/安全レバー不良 MISSING AC BELT /クーラーベルト欠品

CYLINDERS	BOOM	OK
	SWING	—
	ARM	OK
	BUCKET	OK
	BLADE	—
	NOTE	

TURN TABLE	OIL LEAK AT SWIVEL JOINT PIPING/スイベル配管部洩れ
------------	---

CONTROL	HYDRAULIC PUMP	OK
	TRAVEL	OK
	SWING	SWING DRIFT/旋回流れる
	CONTROL	OK
	NOTE	

ATTACHMENT	—
------------	---

REMARK	DAMAGED EXTERIOR / RUSTED/外装破損、サビあり
--------	-------------------------------------

ATTENTION/注意 *For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
*別途修理、洗車の費用がかかる場合があります。ご了承くださいませようお願いします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
*Starting from 1st August 2017,for each successful bid a "Successful Bid Fee" will be charged
*2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました