



GREEN AUCTION

MANLIFT

LotNo	8262003	LOCATION	YOKOHAMA-E
-------	---------	----------	------------

MAKER	ENS	YEAR	2009				
MODEL	ENCL045	HOUR	386	CARRIER HR	—	CARRIER KM	—
S/N	ENCL450076	CASSIS MODEL	—	CASSIS S/N	—		

☐ DOCUMENT/書類 ☐ UNABLE TO TRAVEL(START)/不働車

ENGINE	CARRIER				CRANE				HYDRAULIC (CRANE)	PUMP	—		TYPE OF OUTRIGGER	—		ELECTRICAL	LIGHT	—		
	MODEL				—			MAIN WINCH		—		OUTRIGGER CYLINDER	—		WIPER		—			
	S/N				—			AUX WINCH		—		OUTRIGGER EXTENSION	—		HEATER		—			
	COOLANT	—			—			BOOM EXTENSION		—		SWING	—		A/C		—			
	OIL	—			—			BOOM HOIST		—		CONTROL LEVER	—		BATTERY		OK			
	START	—			—			NOTE						NOTE						
	BLOW-BY	—			—															
	NOISE	—			—															
	NOTE																			
HOOK	CAPACITY	MAIN	— (t)		SUB	— (t)		BOOM	LENGTH	— m		FORK LIFT	TYPE	—		TIRE	SIZE	—		
	NO. OF HOOK	— pcs							CONDITION	—			FORK	LENGTH	— mm		CONDITION	OK		
	WIRE ROPE	—							SHEEVE	—				—			SHOE	—		
	NOTE								NOTE								☐ W/PAD	TYPE	RUBBER	
TRANSMISSION	NO. OF SPEED	F	—		R	—		JIB	NO. OF SEC	— sec		HYDRAULIC	LIFT CYLINDER	—		UNDERCARRIAGE	150 mm	OK		
	SHIFT	—							CONDITON	—			MAST	LENGTH	— mm		PIN BUSH	—		
	OIL	—							NOTE					—			CARRIER ROLLER	OK		
	NOTE																TRACK ROLLER	—		
CAB	—							SAFETY DEVICE	MONITOR	—		BRAKE	FOOT	—		REMARK				
	—								AML	—			PARKING	OK			4.5M			
	—								OVER WIND CUT	—			NOTE							
	NOTE																			

ATTENTION/ 注意

*For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.

*別途修理、洗車の費用がかかる場合があります。ご了承くださいますようお願いいたします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。

*Starting from 1st August 2017,for each successful bid a "Successful Bid Fee" will be charged

*2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました