



GREEN AUCTION

EXCAVATOR

LotNo	2143001	LOCATION	KOBE-N
MAKER	KBELCO	YEAR	1997
MODEL	SK60-3	HOURL	4700
S/N	LE-22328		

☐ DOCUMENT/書類 ☐ UNABLE TO TRAVEL(START)/不働車

ENGINE	MODEL	—
	S/N	—
	COOLANT	OK
	OIL	OK
	START	OK
	BLOW-BY	YES / あり (SLIGHTLY/小)
	NOISE	NO / なし
	EPA	NO / なし
	NOTE	OIL LEAK / オイル漏れ

UNDERCARRIAGE	SHOE	TYPE	STEEL
	☐ W/PAD		
	450 mm	OK	
	PIN BUSH	OK	
	CARRIER ROLLER	OK	
	TRACK ROLLER	OK	
	FRONT IDLER	OK	
	SPROCKET	OK	
	NOTE		

FRONT ATTACHMENT	BOOM	TYPE	STD
			OK
	ARM	TYPE	STD
			OK
	PIPING		—
	BUCKET	TYPE	SKELETON
			OK
	BLADE		—
	PINS	BOOM	OK
		ARM	OK
		BUCKET	LOOSE (SEVERE) / ガタ (大)
	NOTE	BUCKET PIN BUSHINGS DEFECTIVE / バケットピンブッシュ不良 BOOM AND BUCKET LINK REPAIRED. / ブーム、バケットリンク、補修あり	

CAB/CNP	CAB/CNP	OK
	ROPS	NO / なし
	SEAT	OK
	CONTROL LEVER	OK
	A/C OR HEATER	A/C BLOWS WARM AIR / 冷えない
	COMPUTER	—
	MONITOR	—
	BATTERY	OK
	NOTE	DOOR REPLACED WITH WOODEN BOARD / ドアが木の板

CYLINDERS	BOOM	OK
	SWING	—
	ARM	OK
	BUCKET	OK
	BLADE	—
	NOTE	

TURN TABLE	OIL LEAK / オイル漏れ
------------	------------------

CONTROL	HYDRAULIC PUMP	OK
	TRAVEL	OK
	SWING	OK
	CONTROL	OK
	NOTE	

ATTACHMENT	—
------------	---

REMARK	
--------	--

ATTENTION/注意 *For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
*別途修理、洗車の費用がかかる場合があります。ご了承くださいますようお願いいたします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
*Starting from 1st August 2017,for each successful bid a "Successful Bid Fee" will be charged
*2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました