



GREEN AUCTION

WHEEL LOADER

LotNo	3143005	LOCATION	HAKATA-S
MAKER	KOMATSU	YEAR	—
MODEL	WA380-6	HOURL	20065
S/N	WA095-66698	MILE	—

☐ DOCUMENT/書類 ☐ UNABLE TO TRAVEL(START)/不働車

ENGINE	MODEL	—
	S/N	—
	COOLANT	OK
	OIL	OIL LEAKING SLIGHTLY / オイル漏れ小
	START	OK
	BLOW-BY	YES / あり(SLIGHTLY/小)
	NOISE	NO / なし
	EPA	NO / なし
	NOTE	

CABIN/CANOPY	CAB/CNP	OK
	ROPS	YES / あり
	SEAT	OK
	NOTE	

FRAME	MAIN FRAME	OK
	CENTER PIN	OK
	NOTE	

TIRES	SIZE	235-25
	CONDITION	WORN / 摩耗
	NOTE	

BRAKE & STEERING	FOOT BRAKE	OK
	PARKING BRAKE	OK
	STEERING OPERATION	OK
	NOTE	

DIFF.CASE(F)	OK
DIFF.CASE(R)	OK
COUNTER WEIGHT	OK

ELECTRICAL	LIGHT	OK
	WIPER	—
	HEATER	—
	A/C	OK
	BATTERY	OK
	NOTE	

TRANSMISSION	GEAR	OK
	SHIFT	OK
	OIL	MINOR OIL LEAK. / オイルにじみ
	NOTE	SHIFT SHOCK IS LARGE WHEN CHANGING FROM FORWARD TO REVERSE. / 前後進、切替時シフトショック大きい

HYDRAULIC	PUMP	MINOR OIL LEAK. / オイルにじみ
	LIFT CYLINDER	OK
	TILT CYLINDER	OK
	STEERING CYLINDER	OK
	LINE	MINOR OIL LEAK. / オイルにじみ
	NOTE	

BUCKET LOADER	ARM	OK
	PINS	—
	TYPE	STD
	SERIAL	—
	EDGE	OK
	TEETH	—
	GENERAL CONDITION	OK
	NOTE	

BLANK

REMARK

FRONT AND REAR DRIVE SHAFT SEAL, MINOR OIL LEAK. / フロント、リアドライブシャフトシールよりオイルにじみ

ATTENTION/注意 *For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
*別途修理、洗車の費用がかかる場合があります。ご了承くださいますようお願いいたします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
*Starting from 1st August 2017,for each successful bid a "Successful Bid Fee" will be charged
*2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました