



GREEN AUCTION

CRANE

LotNo	5143003	LOCATION	KOBE-N
-------	---------	----------	--------

MAKER	KATO	YEAR	2004				
MODEL	KRM-13H	HOUR	17370	CARRIER HR	—	CARRIER KM	74696KM
S/N	5910246	CASSIS MODEL	KR130	CASSIS S/N	KR130-0246		

☒ DOCUMENT/書類 ☐ UNABLE TO TRAVEL(START)/不働車

ENGINE	CARRIER	CRANE		HYDRAULIC (CRANE)	PUMP	OK	TYPE OF OUTRIGGER	H-TYPE	ELECTRICAL	LIGHT	OK
	MODEL	W04D-TF			MAIN WINCH	OK	OUTRIGGER CYLINDER	OK		WIPER	OK
	S/N	—			AUX WINCH	OK	OUTRIGGER EXTENSION	OK		HEATER	OK
	COOLANT	OK			BOOM EXTENSION	OK	SWING	OK		A/C	OK
	OIL	OK			BOOM HOIST	OK	CONTROL LEVER	OK		BATTERY	OK
	START	OK			NOTE	MINOR OIL LEAK FROM FRONT LEFT OUTRIGGER HORIZONTAL CYLINDER / 左前アウトリガー水平シリンダーより油にじみ				NOTE	
	BLOW-BY	YES / あり									
	NOISE	NO / なし									
	NOTE										

HOOK	CAPACITY	MAIN	13 (t)	SUB	1.4 (t)	BOOM	LENGTH	24.1 m	FORK LIFT	TYPE	—	
	NO. OF HOOK	2 pcs					CONDITION	OK		FORK	LENGTH	— mm
	WIRE ROPE	OK					SHEEVE	OK		MAST	LENGTH	— mm
	NOTE						NOTE					

TRANSMISSION	NO. OF SPEED	F	4	R	1	JIB	NO. OF SEC	1 sec	HYDRAULIC	LIFT CYLINDER	—		
	SHIFT	OK					CONDITON	OK		TILT CYLINDER	—		
	OIL	OK					NOTE				HOIST CYLINDER	—	
	NOTE						NOTE						

CAB	OK	SAFETY DEVICE	MONITOR	FADED LCD DISPLAY / 液晶色褪せ	BRAKE	FOOT	OK
SEAT	OK		AML	OK		PARKING	OK
NOTE			OVER WIND CUT	OK		NOTE	

TIRE	SIZE	275/80R22.5	UNDERCARRIAGE	SHOE	TYPE	—
CONDITION	OK			W/PAD	— mm	
PIN BUSH	—			CARRIER ROLLER	—	
TRACK ROLLER	—			FRONT IDLER	—	
SPROCKET	—		NOTE	FR.SUSPENSION CYLINDER RH,LH, MINOR OIL LEAK / フロントサスペンションシリンダー左右 オイルにじみ		

REMARK						

ATTENTION/ 注意

*For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.

*別途修理、洗車の費用がかかる場合があります。ご了承くださいますようお願いいたします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。

*Starting from 1st August 2017,for each successful bid a "Successful Bid Fee" will be charged

*2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました