



GREEN AUCTION

FORKLIFT

LotNo	7143004	LOCATION	HAKATA-A*
-------	---------	----------	-----------

MAKER	KOMATSU	YEAR	2012				
MODEL	FD25T-17	HOUR	4510	CARRIER HR	—	CARRIER KM	—
S/N	315368	CASSIS MODEL	—	CASSIS S/N	—		

☐ DOCUMENT/書類 ☐ UNABLE TO TRAVEL(START)/不動態

ENGINE	CARRIER	CRANE		HYDRAULIC (CRANE)	PUMP	—	TYPE OF OUTRIGGER	—	ELECTRICAL	LIGHT	OK
	MODEL	4D94LE	—		MAIN WINCH	—	OUTRIGGER CYLINDER	—		WIPER	—
	S/N	54943	—		AUX WINCH	—	OUTRIGGER EXTENSION	—		HEATER	—
	COOLANT	OK	—		BOOM EXTENSION	—	SWING	—		A/C	—
	OIL	OK	—		BOOM HOIST	—	CONTROL LEVER	—		BATTERY	DEAD / あがり
	START	OK	—		NOTE		NOTE	POSSIBLE BATTERY ORALTERNATOR FAILURE. / バッテリーまたはオルタネーター故障の可能性あり。 CANNOT CHARGED. / 充電不可			
	BLOW-BY	NO / なし	—								
	NOISE	NO / なし	—								
	NOTE										

HOOK	CAPACITY	MAIN	—	(t)	SUB	—	(t)	BOOM	LENGTH	—	m
	NO. OF HOOK	—					pcs		CONDITION	—	
	WIRE LOUPE	—					SHEEVE		—		
	NOTE						NOTE				

TRANSMISSION	NO. OF SPEED	F	—	R	—	JIB	NO. OF SEC	—	sec
	SHIFT	—					CONDITON	—	
	OIL	—					NOTE		
	NOTE								

CAB	—	SAFTY DEVICE	MONITOR	—
SEAT	—		AML	—
NOTE			OVER WIND CUT	—

FORK LIFT	HYDRAULIC	TYPE	—		
		FORK	LENGTH	1220	mm
			OK		
		MAST	LENGTH	3000	mm
			LOOSE / ガタ		
BRAKE		LIFT CYLINDER	OK		
		TILT CYLINDER	OK		
		HOIST CYLINDER	OK		
		NOTE			

UNDERCARRIAGE	TIRE	SIZE	550-15		
		CONDITION	—		
		SHOE	W/PAD	TYPE	RUBBER
			—	mm	—
PIN BUSH	—				
CARRIER ROLLER TRACK ROLLER	—				
FRONT IDLER	—				
SPROCKET	—				
NOTE	CORRODED SEVERELY / 腐食大				

REMARK	RUSTY, CORRODED. / サビ 腐食
--------	--------------------------

ATTENTION/ 注意

*For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.

*別途修理、洗車の費用がかかる場合があります。ご了承くださいますようお願いいたします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。

*Starting from 1st August 2017,for each successful bid a "Successful Bid Fee" will be charged

*2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました