



GREEN AUCTION

MANLIFT

LotNo	8143002	LOCATION	YOKOHAMA-E*				
MAKER	AICHI	YEAR	2014				
MODEL	SP10CSN	HOUR	5963	CARRIER HR	—	CARRIER KM	—
S/N	749072	CASSIS MODEL	—	CASSIS S/N	—		

☐ DOCUMENT/書類 ☐ UNABLE TO TRAVEL(START)/不働車

ENGINE	CARRIER	CRANE		HYDRAULIC (CRANE)	PUMP	—	TYPE OF OUTRIGGER	—	ELECTRICAL	LIGHT	—	
	MODEL	4TNV88-ZKAS			MAIN WINCH	—	OUTRIGGER CYLINDER	—		WIPER	—	
	S/N	—			AUX WINCH	—	OUTRIGGER EXTENSION	—		HEATER	—	
	COOLANT	OK			BOOM EXTENSION	—	SWING	—		A/C	—	
	OIL	OK			BOOM HOIST	—	CONTROL LEVER	—		BATTERY	OK	
	START	OK			NOTE			NOTE				
	BLOW-BY	OK										
	NOISE	OK										
NOTE												
HOOK	CAPACITY	MAIN	— (t)	SUB	— (t)	BOOM	LENGTH	— m	FORK LIFT	TYPE	—	
	NO. OF HOOK	— pcs					CONDITION	—		FORK	LENGTH	— mm
	WIRE ROPE	—					SHEEVE	—			—	
	NOTE						NOTE			MAST	LENGTH	— mm
TRANSMISSION	NO. OF SPEED	F	—	R	—	JIB	NO. OF SEC	— sec	HYDRAULIC	LIFT CYLINDER	—	
	SHIFT	—					CONDITON	—		TILT CYLINDER	—	
	OIL	—					NOTE			HOIST CYLINDER	—	
	NOTE									NOTE		
CAB	—	SAFETY DEVICE	MONITOR	—	BRAKE	FOOT	—	REMARK				
	SEAT		—	AML		—	PARKING		—	9.9M	*PUNCHED NO. UNKNOWN (刻印不明)	
	NOTE			OVER WIND CUT		—	NOTE					
				NOTE								

ATTENTION/ 注意

*For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.

*別途修理、洗車の費用がかかる場合があります。ご了承くださいますようお願いいたします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。

*Starting from 1st August 2017,for each successful bid a "Successful Bid Fee" will be charged

*2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました