



GREEN AUCTION

MANLIFT

LotNo	8143006	LOCATION	YOKOHAMA-E
-------	---------	----------	------------

MAKER	ENS	YEAR	2009				
MODEL	ENCL045	HOUR	386	CARRIER HR	—	CARRIER KM	—
S/N	ENCL450076	CASSIS MODEL	—	CASSIS S/N	—		

☐ DOCUMENT/書類 ☐ UNABLE TO TRAVEL(START)/不働車

ENGINE	CARRIER		CRANE		HYDRAULIC (CRANE)	PUMP	—		TYPE OF OUTRIGGER	—		
	MODEL			—		MAIN WINCH	—		OUTRIGGER CYLINDER	—		
	S/N			—		AUX WINCH	—		OUTRIGGER EXTENSION	—		
	COOLANT	—	—			BOOM EXTENSION	—		SWING	—		
	OIL	—	—			BOOM HOIST	—		CONTROL LEVER	—		
	START	—	—			NOTE						
	BLOW-BY	—	—									
	NOISE	—	—									
	NOTE											
HOOK	CAPACITY	MAIN	—	(t)	SUB	—	(t)	BOOM	LENGTH	— m		
	NO. OF HOOK	— pcs							CONDITION	—		
	WIRE ROPE	—							SHEEVE	—		
	NOTE								NOTE			
TRANSMISSION	NO. OF SPEED	F	—	R	—	JIB	NO. OF SEC	— sec				
	SHIFT	—					CONDITON	—				
	OIL	—					NOTE					
	NOTE											
CAB	—							SAFETY DEVICE	MONITOR	—		
SEAT	—								AML	—		
NOTE									OVER WIND CUT	—		
									NOTE			
FORK LIFT	HYDRAULIC	TYPE	—					BRAKE	FOOT	—		
		FORK	LENGTH	— mm			PARKING		OK			
			MAST	LENGTH	— mm				NOTE			
		LIFT CYLINDER		—								
UNDERCARRIAGE	TIRE	SIZE	—					REMARK	4.5M			
		CONDITION	OK									
		SHOE	☐ W/PAD	TYPE	RUBBER							
		150 mm	OK									
UNDERCARRIAGE	TIRE	PIN BUSH	—									
		CARRIER ROLLER	OK									
		TRACK ROLLER	—									
		FRONT IDLER	OK									
UNDERCARRIAGE	TIRE	SPROCKET	OK									
		NOTE										

ATTENTION/ 注意

*For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
*別途修理、洗車の費用がかかる場合があります。ご了承くださいますようお願いいたします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
*Starting from 1st August 2017,for each successful bid a "Successful Bid Fee" will be charged
*2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました