



GREEN AUCTION

DOZER

|       |             |                      |             |
|-------|-------------|----------------------|-------------|
| LotNo | 4143001     | LOCATION             | YOKOHAMA-E* |
| MAKER | CATERPILLAR | YEAR                 | 2010        |
| MODEL | D3K         | HOURL (ON DASHBOARD) | 4343        |
| S/N   | LLL00875    | HOURL (ON ENGINE)    | —           |

☐ DOCUMENT/書類 ☐ UNABLE TO TRAVEL(START)/不働車

|        |         |         |
|--------|---------|---------|
| ENGINE | MODEL   | —       |
|        | S/N     | —       |
|        | COOLANT | OK      |
|        | OIL     | OK      |
|        | START   | OK      |
|        | BLOW-BY | NO / なし |
|        | NOISE   | NO / なし |
|        | EPA     | NO / なし |
|        | NOTE    |         |

|              |         |          |
|--------------|---------|----------|
| CABIN/CANOPY | CAB/CNP | OK       |
|              | ROPS    | YES / あり |
|              | SEAT    | OK       |
|              | BATTERY | OK       |
|              | NOTE    |          |

|           |       |    |
|-----------|-------|----|
| CYLINDERS | LIFT  | OK |
|           | TILT  | OK |
|           | ANGLE | OK |
|           | NOTE  |    |

|                 |    |
|-----------------|----|
| TRANSMISSION    | OK |
| MAIN CLUTCH     | OK |
| STEERING CLUTCH | OK |
| BRAKE           | OK |
| NOTE            |    |

|                    |    |
|--------------------|----|
| MAIN FRAME         | OK |
| TRACK ROLLER FRAME | OK |
| NOTE               |    |

|                  |                  |       |
|------------------|------------------|-------|
| FRONT ATTACHMENT | TYPE             | ANGLE |
|                  | FRONT ATTACHMENT | OK    |
| REAR ATTACHMENT  | TYPE             | —     |
|                  | REAR ATTACHMENT  | —     |
|                  | NOTE             |       |

|               |                                |                |       |                |
|---------------|--------------------------------|----------------|-------|----------------|
| UNDERCARRIAGE | LEFT                           |                | RIGHT |                |
|               | SHOE                           | TYPE           | LGP   | WIDTH — mm     |
|               | <input type="checkbox"/> W/PAD | BRAND NEW / 新品 |       | BRAND NEW / 新品 |
|               | PIN BUSH                       | OK             |       | OK             |
|               | CARRIER ROLLER                 | OK             |       | OK             |
|               | IDLER                          | OK             |       | OK             |
|               | TRACK ROLLER                   | OK             |       | OK             |
|               | SPROCKET                       | OK             |       | OK             |
|               | NOTE                           | RUSTY / サビ     |       |                |

|                               |  |
|-------------------------------|--|
| BLANK                         |  |
| REMARK                        |  |
| MAIN BOX MISSING. / メインボックス欠品 |  |

ATTENTION/注意 \*For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.  
\*別途修理、洗車の費用がかかる場合があります。ご了承くださいますようお願いいたします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。  
\*Starting from 1st August 2017,for each successful bid a "Successful Bid Fee" will be charged  
\*2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました