



GREEN AUCTION

CRANE

LotNo	5143001	LOCATION	KOBE-N
-------	---------	----------	--------

MAKER	TADANO	YEAR	2000				
MODEL	TR-100M-1	HR	5007	CARRIER	—	CARRIER	154658KM
S/N	FC1577	CASSIS	TR100	CASSIS	—		

☒ DOCUMENT/書類 ☐ UNABLE TO TRAVEL(START)/不働車

ENGINE	CARRIER	CRANE		HYDRAULIC (CRANE)	PUMP	OK	TYPE OF OUTRIGGER	H-TYPE	ELECTRICAL	LIGHT	OK
	MODEL	W04D-TC	—		MAIN WINCH	OK	OUTRIGGER CYLINDER	NOTE		WIPER	—
	S/N	—	—		AUX WINCH	OK	OUTRIGGER EXTENSION	OK		HEATER	—
	COOLANT	OK	—		BOOM EXTENSION	OK	SWING	OK		A/C	OK
	OIL	OK	—		BOOM HOIST	OK	CONTROL LEVER	OK		BATTERY	OK
	START	OK	—		NOTE	FRONT OUTRIGGER CYLINDERS: SLIGHT OIL WEEPING / 前左右アウトリガーシリンダー(ジャッキアップ)油にじみ				NOTE	
	BLOW-BY	YES / あり(SLIGHTLY/小)	—								
	NOISE	NO / なし	—								
NOTE	MINOR OIL LEAK / オイルにじみ										

HOOK	CAPACITY	MAIN	4.9 (t)	SUB	1.4 (t)	BOOM	LENGTH	—	m	FORK LIFT	TYPE	—
	NO. OF HOOK	2		pcs	CONDITION		OK	FORK	LENGTH		—	mm
	WIRE ROPE	OK		SHEEVE	OK		MAST	LENGTH	—		mm	
	NOTE			NOTE								

TRANSMISSION	NO. OF SPEED	F	4	R	1	JIB	NO. OF SEC	—	sec	HYDRAULIC	LIFT CYLINDER	—
	SHIFT	OK		CONDITON	OK		TILT CYLINDER	—				
	OIL	OK		NOTE			HOIST CYLINDER	—				
	NOTE	MINOR OIL LEAK / オイルにじみ					NOTE					

CAB	OK	SAFETY DEVICE	MONITOR	OK	BRAKE	FOOT	OK
SEAT	DEFECT / 破れ		AML	OK		PARKING	OK
NOTE			OVER WIND CUT	OK		NOTE	

TIRE	SIZE	11R22.5 16PR	UNDERCARRIAGE	REMARK
CONDITION	OK			
SHOE	TYPE	—		
W/PAD	— mm			
PIN BUSH	—		CARRIER ROLLER	—
TRACK ROLLER	—		FRONT IDLER	—
SPROCKET	—		NOTE	ACCUMULATOR ABNORMAL PRESSURE DROP. (WORKING IS OK) / アキュムレータ圧力異常降下表示, 動作可
NOTE				

ATTENTION/ 注意

*For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.

*別途修理、洗車の費用がかかる場合があります。ご了承くださいますようお願いいたします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。

*Starting from 1st August 2017,for each successful bid a "Successful Bid Fee" will be charged

*2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました