



GREEN AUCTION

EXCAVATOR

LotNo	2143012	LOCATION	YOKOHAMA-E
MAKER	CATERPILLAR	YEAR	2012
MODEL	320D-E	HOURL	9598
S/N	BWZ07491		

☐ DOCUMENT/書類 ☐ UNABLE TO TRAVEL(START)/不動車

ENGINE	MODEL	C6.4
	S/N	GDC70383
	COOLANT	OK
	OIL	OK
	START	NOT TESTED / 未確認
	BLOW-BY	NOT TESTED / 未確認
	NOISE	NOT TESTED / 未確認
	EPA	NO / なし
	NOTE	

UNDERCARRIAGE	SHOE	TYPE	STEEL
	☐ W/PAD		
	600 mm	OK	
	PIN BUSH	OK	
	CARRIER ROLLER	OK	
	TRACK ROLLER	OK	
	FRONT IDLER	OK	
	SPROCKET	OK	
	NOTE		

FRONT ATTACHMENT	BOOM	TYPE	STD
			OK
	ARM	TYPE	STD
			OK
	PIPING		-
	BUCKET	TYPE	STD
			OK
	BLADE		-
	PINS	BOOM	OK
		ARM	OK
		BUCKET	OK
	NOTE		

CAB/CNP	CAB/CNP	OK
	ROPS	NO / なし
	SEAT	OK
	CONTROL LEVER	-
	A/C OR HEATER	OK
	COMPUTER	OK
	MONITOR	OK
	BATTERY	DEAD / あがり
	NOTE	

CYLINDERS	BOOM	OK
	SWING	-
	ARM	OIL LEAKING SEVERELY / オイル漏れ大
	BUCKET	OK
	BLADE	-
	NOTE	START ENGINE, OIL LEAK ARE SEVERE. / E/G始動するとオイル漏れ激しい

TURN TABLE	OK
------------	----

CONTROL	HYDRAULIC PUMP	OK
	TRAVEL	OK
	SWING	OK
	CONTROL	OK
	NOTE	

ATTACHMENT	-
------------	---

REMARK

*NEED REPAIR. / 要修理 *NEED WASHING / 要洗車
*REPAIRS ARE REQUIRED FOR SHIPPING. (船積みの場合は修理必須)
*NEED LIFT CHARGE FOR RELEASING (別途リフトチャージ必要)
*NO FULL CONDITION CHECK. / 動作未確認

ATTENTION/注意 *For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
*別途修理、洗車の費用がかかる場合があります。ご了承くださいますようお願いいたします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
*Starting from 1st August 2017,for each successful bid a "Successful Bid Fee" will be charged
*2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました