



GREEN AUCTION

## MINI EXCAVATOR

|       |          |          |        |
|-------|----------|----------|--------|
| LotNo | 1263006  | LOCATION | KOBE-N |
| MAKER | KOMATSU  | YEAR     | 2014   |
| MODEL | PC38UU-5 | HOURL    | 924    |
| S/N   | 16466    |          |        |

☐ DOCUMENT/書類 ☐ UNABLE TO TRAVEL(START)/不働車

|        |         |             |  |
|--------|---------|-------------|--|
| ENGINE | MODEL   | 3D88E-6BPCB |  |
|        | S/N     | 28768       |  |
|        | COOLANT | OK          |  |
|        | OIL     | OK          |  |
|        | START   | OK          |  |
|        | BLOW-BY | NO / なし     |  |
|        | NOISE   | NO / なし     |  |
|        | EPA     | NO / なし     |  |
|        | NOTE    |             |  |

|               |                                |      |        |
|---------------|--------------------------------|------|--------|
| UNDERCARRIAGE | SHOE                           | TYPE | RUBBER |
|               | <input type="checkbox"/> W/PAD |      |        |
|               | 300 mm                         | OK   |        |
|               | PIN BUSH                       | OK   |        |
|               | CARRIER ROLLER                 | OK   |        |
|               | TRACK ROLLER                   | OK   |        |
|               | FRONT IDLER                    | OK   |        |
|               | SPROCKET                       | OK   |        |
|               | NOTE                           |      |        |

|                  |        |        |                         |
|------------------|--------|--------|-------------------------|
| FRONT ATTACHMENT | BOOM   | TYPE   | OFF-SET                 |
|                  |        | OK     |                         |
|                  | ARM    | TYPE   | LONG                    |
|                  |        | OK     |                         |
|                  | PIPING | -      |                         |
|                  | BUCKET | TYPE   | STD                     |
|                  |        | OK     |                         |
|                  | BLADE  | OK     |                         |
|                  | PINS   | BOOM   | OK                      |
|                  |        | ARM    | LOOSE (SLIGHT) / ガタ (小) |
|                  |        | BUCKET | OK                      |
|                  | NOTE   |        |                         |

|         |               |           |  |
|---------|---------------|-----------|--|
| CAB/CNP | CAB/CNP       | OK        |  |
|         | ROPS          | NO / なし   |  |
|         | SEAT          | OK        |  |
|         | CONTROL LEVER | OK        |  |
|         | A/C OR HEATER | -         |  |
|         | COMPUTER      | OK        |  |
|         | MONITOR       | OK        |  |
|         | BATTERY       | WEAK / 弱い |  |
|         | NOTE          |           |  |

|           |        |    |
|-----------|--------|----|
| CYLINDERS | BOOM   | OK |
|           | SWING  | OK |
|           | ARM    | OK |
|           | BUCKET | OK |
|           | BLADE  | OK |
|           | NOTE   |    |

|            |    |
|------------|----|
| TURN TABLE | OK |
|------------|----|

|         |                |    |
|---------|----------------|----|
| CONTROL | HYDRAULIC PUMP | OK |
|         | TRAVEL         | OK |
|         | SWING          | OK |
|         | CONTROL        | OK |
|         | NOTE           |    |

|            |   |
|------------|---|
| ATTACHMENT | - |
|------------|---|

|                           |
|---------------------------|
| REMARK                    |
| 0.9TON ARM CRANE / クレーン付き |

ATTENTION/注意 \*For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.  
\*別途修理、洗車の費用がかかる場合があります。ご了承くださいますようお願いいたします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。  
\*Starting from 1st August 2017,for each successful bid a "Successful Bid Fee" will be charged  
\*2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました