



GREEN AUCTION

FORKLIFT

LotNo	7263001	LOCATION	HAKATA-A*
-------	---------	----------	-----------

MAKER	KOMATSU	YEAR	2003				
MODEL	FD25C-15	HOUR	3374	CARRIER HR	—	CARRIER KM	—
S/N	575951	CASSIS MODEL	—	CASSIS S/N	—		

☐ DOCUMENT/書類 ☐ UNABLE TO TRAVEL(START)/不働車

ENGINE	CARRIER		CRANE		HYDRAULIC (CRANE)	PUMP	—		TYPE OF OUTRIGGER	—		ELECTRICAL	LIGHT	OK		
	MODEL	4D94E		—		MAIN WINCH	—		OUTRIGGER CYLINDER	—			WIPER	—		
	S/N	25270		—		AUX WINCH	—		OUTRIGGER EXTENSION	—			HEATER	—		
	COOLANT	—		—		BOOM EXTENSION	—		SWING	—			A/C	—		
	OIL	OK		—		BOOM HOIST	—		CONTROL LEVER	—			BATTERY	OK		
	START	OK		—		NOTE							NOTE			
	BLOW-BY	YES / あり		—												
	NOISE	NO / なし		—												
	NOTE	WHITE SMOKE / 白煙あり RADIATOR COVER CANNOT BE REMOVED. / ラジエーターカバー取り外し不可														
HOOK	CAPACITY	MAIN	— (t)		SUB	— (t)		BOOM	LENGTH	— m		TIRE	SIZE	7.00 R12		
	NO. OF HOOK	— pcs					CONDITION		—		CONDITION		—			
	WIRE LOUPE	—					SHEEVE		—		SHOE		TYPE RUBBER			
	NOTE								W/PAD	— mm						
TRANSMISSION	NO. OF SPEED	F	—		R	—		JIB	NO. OF SEC	— sec		UNDERCARRIAGE	PIN BUSH	—		
	SHIFT	—					CONDITON		—		CARRIER ROLLER		—			
	OIL	—					NOTE				TRACK ROLLER		—			
	NOTE						SAFETY DEVICE		MONITOR	—			FRONT IDLER	—		
CAB	—					AML		—		SPROCKET	—					
SEAT	—					OVER WIND CUT		—		NOTE	CORRODED SEVERELY. / 腐食大					
NOTE						NOTE				REMARK						
BRAKE	FOOT	STUCK / 固着					REMARK	ENGINE RPM SURGES VIOLENTLY AFTER STARTING DUE TO A STUCK ACCELERATOR. / アクセル固着のため、始動後回転数激しい OVERALL CORRODED. / 全体的に腐食あり								
	PARKING	NOT WORKING. / 効かない														
	NOTE															

ATTENTION/ 注意

*For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
*別途修理、洗車の費用がかかる場合があります。ご了承くださいますようお願いいたします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
*Starting from 1st August 2017,for each successful bid a "Successful Bid Fee" will be charged
*2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました